PC-DMIS Inspection Planner

PC-DMIS™ Enhancement for Versions 3.7 and Above

by

Wilcox Associates, Inc.

http://www.wilcoxassoc.com

Last Updated: April 28, 2006

Table Of Contents

PC-D	MIS Inspection Planner	1
Ins	pection Planner: Introduction	1
Us	ing PC-DMIS Inspection Planner for CATIA V5	2
I	nstalling Inspection Planner for CATIA V5	2
٦	To start the PC-DMIS Inspection Plan application	2
I	P_Tools Toolbar	3
I	P_Features Toolbar	6
I	P_Commands Toolbar1	5
E	Editing your Inspection Plan in CATIA 52	1
Us	ing PC-DMIS Inspection Planner for SolidWorks2	2
I	nstalling Inspection Planner for SolidWorks2	2
٦	To start the PC-DMIS Inspection Plan application2	2
(Creating Features2	:6
(Constructing Datum Features	5
(Creating Alignments	5
(Constructing GD&T Features	9
(Creating Location Dimensions3	9
(Constructing Features4	.1
I	nserting Comments4	.2
Us	ing PC-DMIS Inspection Planner for Unigraphics4	.3
٦	To install the PC-DMIS Inspection Planner4	.3
٦	Fo start the PC-DMIS Inspection Plan application4	3

To Create a New PC-DMIS Inspection Plan	44
Creating Features	45
Creating Commands for Datum	54
Creating Alignments	55
Creating Tolerances	57
Creating Location Dimensions	58
Constructing Features	59
Inserting Comments	60
Displaying the Inspection Plan	60
Exporting Your Inspection Plan	61
Using Inspection Planner within PC-DMIS	62
Importing the Inspection Plan	62
Performing the Path Optimization	64
Dual Arm Path Optimization	66
Path Optimization Summary	67
Void Detection	68
Automatically Inserting Move Commands	69
Inspection Planner Parameters and Rules	70
Creating and Modifying an Inspection Planner Default (IPD) file	70
Inspection Planner Rules (IPR) script	72
Appendix A: IP - Constructed Features	74
Appendix B: Using the Generic Parser to Import ASCII Files	76
Importing an ASCII File	77

Step 1: Excluding Data	78
Step 2: Defining Delimiters	79
Step 3: Feature Type Mapping and Field Assignment	81
Previewing the ASCII File	82
Glossary	85
Index	87

Inspection Planner: Introduction

PC-DMIS Inspection Planner, or IP, only works with PC-DMIS Version 3.6 and above.

PC-DMISTM Inspection Planner (*IP*) is an add-in module that works in conjunction with a supported CAD package and PC-DMIS to aid the Design Engineer or Quality Engineer in designing a plan that determines which features of the geometry and GD&T/dimension to use in the inspection process.

Inspection Planner (*IP*) uses the PC-DMIS CAD engine, providing access to IGES, STEP, and the other translators, as well as PC-DMIS's supported Direct CAD Interfaces[™]. This gives you wide coverage of available CAD engines and systems.

Since IP runs inside your CAD package, it cuts your learning curve since you will only need to use a small portion of PC-DMIS for Windows to generate the part program.

Inspection Planner supports these CAD packages:

- CATIA V5
- SolidWorks
- Unigraphics

This manual will walk you through the steps to get IP running with your CAD package and will discuss how to use IP commands inside PC-DMIS to automatically generate the PC-DMIS part program.

This documentation covers these topics:

- Using PC-DMIS Inspection Planner for CATIA V5
- Using PC-DMIS Inspection Planner for SolidWorks
- Using PC-DMIS Inspection Planner for Unigraphics
- Using Inspection Planner within PC-DMIS
- Inspection Planner Parameters and Rules

Using PC-DMIS Inspection Planner for CATIA V5

This topic describes how to install and use PC-DMIS Inspection Plan within CATIA V5. IP allows you to perform various sub tasks needed to create an Inspection Plan that you can either store with your CAD data or export as a text file.

The Inspection Planner option must be enabled on your portlock to use the Inspection Planner capabilities for CATIA 5.

Installing Inspection Planner for CATIA V5

- Log on to the Wilcox ftp site: <u>ftp.wilcoxassoc.com</u>. Browse to the Inspection Planner/CatiaV5/ directory. Download the required CATIA V5 Inspection Planner install file. Download the **InspectionPlanner_CATIA_V5_R13.exe** for CATIA V5 version 13 for CATIA V5 release 13 or **InspectionPlanner_CATIA_V5_R14.exe** for CATIA V5 release 14 to a specified directory on your hard drive.
- 2. Double-click on the InspectionPlanner_CATIA_V5_R1X.exe for CATIA V5 version 13 or 14 file to begin the installation of IP for CATIA V5
- The Setup program will prompt you to select the location of the CATIA V5 installation directory. Browse to the CATIA installation directory (e.g. C:\Program Files\Dassault Systemes\B14), and click OK.
- 4. You will then be prompted to select the location of the PC-DMIS installation directory. Browse to the PC-DMIS installation directory, and click **OK**.
- 5. The Setup program will then prompt you to select the location where PC-DMIS Inspection Planner for CATIA V5 will be installed. The default directory might look something like this: C:\PCDMISW\InspectionPlanner\CatiaV5.
- 6. Next, setup will prompt you to verify the location of the CATIA install and the directory for the IP installation.
- 7. Click **OK** if everything is correct.
- 8. The Setup program now copies files for **PC-DMIS Inspection Planner for CATIA V5** to this newly created directory.

The Setup program will check to see if the needed file structure and files for CATIA V5 are properly installed in the directory you previously specified. An error will occur if the files do not exist. If everything installs correctly, then an **InspectionPlannerTest** shortcut will be added to the desktop.

Important: The new shortcut must be used to start CATIA V5 to set up the proper environment for Inspection Planner to work within your CATIA V5 install.

To start the PC-DMIS Inspection Plan application

To start a PC-DMIS Inspection Plan session from within your CATIA V5 session, follow this procedure:

 Start CATIA V5 using the InspectionPlanner_R** shortcut which should be on the desktop. You must use this shortcut rather than the regular CATIA V5 shortcut for Inspection Planner to work correctly 2. Within CATIA's Product Structure or Part Design workbenches, you should see three new toolbars; **IP_Tools**, **IP_Features**, and **IP_Commands**.



Once you have started the PC-DMIS Inspection Planner application, you may create, list, and edit IP features, commands, and Inspection Plans.

IP_Tools Toolbar

The **IP_Tools** toolbar contains a number of miscellaneous tools for use in creating, editing, exporting, and using Inspection Plans.

Creating a New Inspection Plan

To create a new PC-DMIS Inspection Plan, follow this procedure:

- 1. Select the New Inspection Plan icon on the toolbar.
- 2. The **Plan** dialog box appears.



Plan dialog box

- 3. Type a name for the Plan in the **Label** box.
- 4. Click **OK** to save the Plan's name. This creates a new **InspectionPlanner** node in the feature tree. This node has two children, **Plans** and **IP Features**. The new plan is placed under the **Plans** node.

PC-DMIS Inspection Planner



Changing the order of the Items in a Plan

To change the order of the commands in a selected plan, follow this procedure:

Es

- 1. Select the **Reorder Commands** icon on the toolbar.
- 2. The **Re-Order Commands** dialog box appears.



Re-Order Commands dialog box

- 3. Select the plan to edit from the **Plan** drop-down list.
- 4. All the items in the plan will appear in the list.
- 5. To change the order of the items, select an item, and the click the **up arrow** to move it up in the list, or click the **down arrow** to move it down in the list.
- 6. Select the **OK** button to apply the changes to the plan.

Exporting a Plan to a File

To Export a previously created Inspection Plan for use within PC-DMIS, follow this procedure:

- 1. Select the **Text Output** icon on the toolbar.
- 2. The Plan Selection dialog box appears.



Plan Selection dialog box

- 3. Select the plan to export.
- 4. Click the **OK** button. A standard Windows **Save File** dialog box appears.

Save As	-				? ×
Save jn:	227469		•	+ 🗈 💣 🗔-	
My Recent Documents Desktop) hex_feature	s_catpart_Plan 1.ip			
My Documents					
My Computer					
	1				
My Network Places	File pame:	plan1[ip		- 1	Save
	Save as type:	Inspection Planner		× .	Cancel

Windows save file dialog box

- 5. Browse to the location where you would like to save the file. Type a name for the Inspection Planner file in the **File name** box
- 6. Click **Save** to export the file. This text file can be imported into PC-DMIS. See "<u>Importing</u> <u>the Inspection Plan</u>".

Updating Features

Select the **Update** icon on the toolbar. This will update all of the features if the model geometry or assembly has changed.

Activating a Plan

To ensure that all Features or Commands are added to the appropriate plan, follow these steps:

- 1. Select the Activate Plan icon on the toolbar.
- 2. Select a plan from the feature tree (As discussed in "Creating a New Inspection Plan").
- 3. The selected plan is now the active plan.

IP_Features Toolbar

Using the **IP_Features** toolbar you can create and add features to an existing plan. Or, if you don't have a plan yet, you can create a feature and IP will automatically create a new plan for you.

Once you have created a new Inspection Plan, you can create features for that Inspection Plan. The general method of creating features is as follows:

- 1. From the **IP_Features** toolbar, select the feature type you want to create (listed below). A dialog box, specific to the feature you selected, appears. Inspection Planner supports the following features:
 - Point
 - Line 🜌
 - Edge Point
 - Plane
 - Cylinder
 - Sphere
 - Circle
 - Round Slot

 - Square Slot
- 2. Using the mouse, select the face, edge, or vertex from the CAD display that will be used for the feature. You may be asked to select with the mouse again, depending on the type of feature you are defining and the CAD object first selected. The **Open Feature** dialog box will display the correct values provided from the CAD data. You can edit these values as needed.
- Click the OK button to accept your changes and create the feature. This feature will be added to the IP Features node in the Inspection Planner tree as well as to the currently active plan.

If no plan has been created, then creating any feature or command will automatically create a new plan and place that feature or command in that plan.

The dialog box for each specific type of feature is explained below:

Creating a Point Feature

- 1. Select the **Point** icon on the toolbar.
- 2. The IP Point Feature dialog box appears.
- 3. Indicate the location of the point feature by clicking on any surface. The X, Y, and Z values for the selected point appear in the dialog box.

Point F	eature	_ IX
Insert	Label Pt1 In Plan Plan :	3
Poin	2	
X	134.08	
ΠY	11.037	
□z	21	
Norr	nal —	
IO		
JO		
K 1		
	Reverse	
🔎 cor	nstrain to geol	metry
Find	Point	
	🗿 ок	Cancel

IP Point Feature dialog box

- 4. Change the Label for the point if needed.
- 5. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 6. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 7. Selecting **Reverse** will reverse the direction of the vector.
- 8. If you select the **constrain to geometry** check box, IP will tie this feature to the selected geometry. If the geometry changes, then so will the feature.
- 9. If you change the values, then the values no longer reflect the model geometry. You must either select the **Find Point** button to find the closest point on the geometry, or deselect the **constrain to geometry** check box before you can create the point.
- 10. Click **OK** to accept the current values and add the point feature to the current Inspection Plan.

Creating a Line Feature

- Select the Line icon on the toolbar.
- 2. The IP Line Feature dialog box appears.
- 3. Indicate the location of the start point of the line feature by clicking the first point on any surface. IP inserts that start point location into the dialog box.
- 4. Indicate the location of the end point of the line feature by clicking a second point on any surface. IP inserts that end point location into the dialog box.

Line Feature	
Label Ln1	
Insert In Plan Plan 3	
Start Point	
X 100.4	
YO	
Z -3.911	
End Point	
X 231.63	
YO	
Z -7.6489	
Surface Vector	=
IO	
J1	
KO	
Reverse	<u> </u>
🔎 constrain to geomet	ry
find	
💽 🧿 ок	Cancel

IP Line Feature dialog box

- 5. Change the **Label** for the line if needed.
- 6. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 7. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 8. Selecting **Reverse** will reverse the direction of the vector.
- 9. If you select the **constrain to geometry** check box, IP will tie this feature to the selected geometry. If the geometry changes, then so will the feature.
- 10. If you change the values, then the values no longer reflect the model geometry. You must either select the **find** button to find the closest point on the geometry, or deselect the **constrain to geometry** check box before you can create the line.
- 11. Click **OK** to accept the current values and add the line feature to the current Inspection Plan.

Creating an Edge Point Feature

- 1. Select the Edge Point icon on the toolbar.
- 2. The IP Edge Feature dialog box appears.
- Indicate the location of the edge point feature by clicking on any surface near an edge. The point will snap to the nearest edge of the surface. IP inserts the point's location into the dialog box.

Edge Feature	_ 🗆 🗵
Label Edg1	
Insert In Plan Plan 3	
Point	
X 215.26	
YO	
Z -1	
Surface Vector	
IO	
JO	
K 1	
Reverse Vector	
Edge Vector	
IO	
J -1	
KO	
Reverse Vector	
🧧 constrain to geomet	ry
find point	
	Cancel
	Cancer

IP Edge Feature dialog box

- 4. Change the Label for the edge point if needed.
- 5. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 6. Change the values for the **XYZ** coordinates and the **IJK** vector values as needed.
- 7. Selecting Reverse will reverse the direction of the vector.
- 8. If you select the **constrain to geometry** check box, IP will tie this feature to the selected geometry. If the geometry changes, then so will the feature.
- 9. If you change the values, then the values no longer reflect the model geometry. You must either select the **find point** button to find the closest point on the geometry, or deselect the **constrain to geometry** check box before you can create the point.
- 10. Click **OK** to accept the current values and add the edge point feature to the current Inspection Plan.

Creating a Plane Feature

- 1. Select Plane icon on the toolbar.
- 2. The IP Plane Feature dialog box appears.
- 3. Indicate the location of the plane feature by clicking any surface. IP inserts the plane's location and vector data into the dialog box.

Plane Feature	
Label Pin1 Insert In Pian 9	
Point	_
X 115.77	
Y 12.132	
Z 21	
Normal	
IO	
J0	
K 1	
Reverse	
constrain to geometr	Y
	Cancel

IP Plane Feature dialog box

- 4. Change the Label for the plane if needed.
- 5. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 6. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 7. Selecting **Reverse** will reverse the direction of the vector.
- 8. If you select the **constrain to geometry** check box, IP will tie this feature to the selected geometry. If the geometry changes, then so will the feature.
- 9. If you change the values, then the values no longer reflect the model geometry. You must either select the **find** button to find the closest point on the geometry, or deselect the **constrain to geometry** check box before you can create the plane.
- 10. Click **OK** to accept the current values and add the plane feature to the current Inspection Plan.

Creating a Cylinder Feature

- 1. Select the **Cylinder** icon on the toolbar.
 - bar. 🔜
- 2. The IP Cylinder Feature dialog box appears.
- 3. Indicate the location of the cylinder feature by clicking the cylindrical surface of a cylinder. IP inserts the cylinder's origin and axis into the dialog box.

Cylinder Feature	
Label Cyl1	-
Insert In Plan Plan 3	
Internal Cylinder	P
Origin	
× 93.772	Sec. Star
Y 19.594	
Z 21	
Axis	
IO	
J0	
K 1	
Reverse	
Diameter 15	
Length 35	100
Top Offset 0	
Bottom Offset 0	
🔎 constrain to geomet	ry
🦰 🔿 ок	Cancel
	Cancer

IP Cylinder feature dialog box

- 4. Change the **Label** for the cylinder if needed.
- 5. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 6. Select either an Internal Cylinder or External Cylinder.
- 7. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 8. Selecting **Reverse** will reverse the direction of the vector.
- 9. Specify the **Diameter** and **Length** of the cylinder.
- 10. Specify the **Top Offset**. The **Top Offset** value will increase or decrease the length of the cylinder on the end where the vector is defined. A positive value will increase the length of the cylinder in the direction of the vector.
- 11. Specify the **Bottom Offset**. The **Bottom Offset** value will increase or decrease the length of the cylinder on the opposite end from where the vector is defined. A positive vector will decrease the length of the cylinder in the direction of the vector.
- 12. If you select the **constrain to geometry** check box, IP will tie this feature to the selected geometry. If the geometry changes, then so will the feature.
- 13. If you change the values, then the values no longer reflect the model geometry. You must deselect the **constrain to geometry** check box before you can create the cylinder.
- 14. Click **OK** to accept the current values and add the cylinder feature to the current Inspection Plan.

Creating a Sphere Feature

- 1. Select the **Sphere** icon on the toolbar.
- 2. The IP Sphere Feature dialog box appears.
- 3. Indicate the location of the sphere by selecting a circular edge or spherical face of the sphere. IP calculates the sphere's location and vector from where you clicked.

5phere Feature	
Label Sph1	-
Insert In Plan Plan 3	
	AVE SAVE
	-
O Internal Sphere	
External Sphere	
Center	
X 168.68	
Y 45.659	
Z 21	
Vector	_
IO	
10 10	
K 1	
Dismahaulus	
Diameter 12,7	
constrain to geome	etry
🤜 🎱 ок	Cancel
	-

IP Sphere feature dialog box

- 4. Change the **Label** for the sphere if needed.
- 5. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 6. Select either an Internal or External Sphere.
- 7. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 8. Specify the **Diameter** of the sphere.
- 9. If you select the **constrain to geometry** check box, IP will tie this feature to the selected geometry. If the geometry changes, then so will the feature.
- 10. If you change the values, then the values no longer reflect the model geometry. You must deselect the **constrain to geometry** check box before you can create the sphere.

The vector is never tied to the geometry, and can be modified while keeping the sphere constrained to the model geometry. Therefore, constraining to geometry has not effect on Vector values.

11. Click **OK** to accept the current values and add the sphere feature to the current Inspection Plan.

Creating a Circle Feature

- 1. Select the **Circle** icon on the toolbar.
- 2. The IP Circle Feature dialog box appears.
- 3. Indicate the location of the circle feature by clicking a circular edge or cylindrical surface of the circle feature. IP inserts the circle's axis and center into the dialog box.

Circle Feature	
Label Cir1 Insert In Plan	-
 Iternal Circle External Circle 	_
Center X	
K 1 Reverse	
Diameter 1 Offset 0	
constrain to geome	
	Cancel

IP Circle feature dialog box

- 4. Change the Label for the circle if needed.
- 5. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 6. Select either an Internal or External Circle.
- 7. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 8. Selecting **Reverse** will reverse the direction of the vector.
- 9. Specify the **Diameter** and **Offset**. The **Offset** value will transform the center of the circle along the feature's vector by the specified positive or negative amount.
- 10. If you select the **constrain to geometry** check box, IP will tie this feature to the selected geometry. If the geometry changes, then so will the feature.
- 11. If you change the values, then the values no longer reflect the model geometry. You must deselect the **constrain to geometry check box** before you can create the circle.
- 12. Click **OK** to accept the current values and add the circle feature to the current Inspection Plan.

Creating Round or Square Slot Features

- 1. Select the **Round Slot** or **Square Slot** icon on the toolbar.
- 2. The **IP Slot Feature** dialog box appears. The selected slot type will be selected based on the icon that was clicked. You can change the slot type inside the dialog box as well.
- 3. Indicate the location of the slot by selecting the face that the slot is cut out of. Select near the edge of the slot. IP will insert the location and vector data into the dialog box.

Slot Feature	
Label SI2	
Insert In Plan Plan 3	
Slot Type	1
Square Slot	
O Round Slot	
Location	
X 69.858	
Y 23.335	
Z 21	
Vector 1	1
IO	
10	
K 1	
Reverse	
Vector 2	
I -0.70711	
J-0.70711	
Ko	
Reverse	
Width 11	
Length 37	
	_
Iternal Slot	
O External Slot	
constrain to geometry	
🔜 💿 ок 🗵	Cancel

IP Slot Feature dialog box

- 4. Change the **Label** for the slot if needed.
- 5. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 6. Select either Round or Square Slot.
- 7. Change the values for the XYZ coordinates and the IJK vector values as needed.

- 8. Selecting **Reverse** will reverse the direction of the vector.
- 9. Specify the **Width** and **Length** of the slot.
- 10. Select either Internal or External Slot.
- 11. If you select the **constrain to geometry** check box, IP will tie this feature to the selected geometry. If the geometry changes, then so will the feature.
- 12. If you change the values, then the values no longer reflect the model geometry. You must deselect the **constrain to geometry check box** before you can create the slot.
- 13. Click **OK** to accept the current values and add the slot feature to the current Inspection Plan.

IP_Commands Toolbar

Using the **IP_Commands** toolbar, you can create, translate and rotate alignments. Adding location dimensions and constructed features as well as inserting comments into your part program is also done from the **IP_Commands** Toolbar.

Creating Alignments

Once you have created your features, you can create or modify alignments.

- 1. Select the Alignment icon on the toolbar.
- 2. The IP Alignment Command dialog box appears.

	ent Command	?
L	abel Aln1	
Insert in I	Plan Plan 1	
Primary	,	
Feature	Pln1	Remove
Level to	+7	-
-Second		
Feature	Ln1	Remove
Rotate to	×+X	-
About	Z Axis	•
X Origin	Pt1	Remove
Y Origin	Ln1	Remove
Z Origin	Pln1	Remove
	-	1
100	Ok	Cancel

IP Alignment Command dialog box

- 3. If needed, type an ID for this alignment in the **Label** box.
- 4. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 5. In the **Primary** alignment area, indicate the axis you want to **Level to** for the primary alignment IP Feature. Select the proper axis in the drop-down list. The default axis is **+Z**.
- 6. Next, select the primary alignment IP Feature by selecting the label for it from the model window or by selecting it from the feature tree.

- 7. In the **Secondary** alignment section, indicate the axis to **Rotate to** and the axis to rotate **About** for the secondary alignment IP feature. Select the proper axes in the drop-down lists.
- 8. Select the secondary alignment IP Feature by selecting the label for it in the model window or by selecting it in the feature tree.
- 9. As you select the primary and secondary IP features, they are also set, as appropriate, in the **X**, **Y**, and **Z Origin** boxes.
- 10. You can change any of the IP features by first selecting the edit box for that feature and then selecting a new IP feature.
- 11. Click **OK** to accept the current values and add the **IP Alignment** command to the current Inspection Plan.

Translating Alignments

You can translate (or move) your Inspection Plan's current alignment by an offset distance.

- 1. Select the **Translation** icon on the toolbar.
- 2. The IP Translation Command dialog box appears.

Label	Aln1
Insert in Pla	Plan 1
X Axis	5
Y Axis	10
Z Axis	12.5

IP Translation Command dialog box

- 3. If needed, type an ID for the alignment you want to translate in the Label box.
- 4. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 5. Type the values for the translation along the X, Y, and Z axes in the X, Y, and Z Axis boxes.
- 6. Click **OK** to accept the current values and add the IP translation command to the current Inspection Plan's alignment.

Rotating Alignments

You can rotate your Inspection Plan's current alignment by a specified angle.

- 1. Select the **Rotation** icon on the toolbar.
- 2. The IP Rotation Command dialog box appears.

Label	Aln1	
Insert in Plan	Plan 1	
Angle	30	
Axis	X Axis	_
	X Axis	
	Y Axis	

IP Rotation Command dialog box

- 3. If needed, type an ID for the alignment you want to rotate in the Label box.
- 4. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 5. Type the angle of the rotation in the **Angle** box.
- 6. Select the axis (X, Y, or Z) you want to rotate about in the Axis box.
- 7. Click **OK** to accept the current values and add the **IP Rotation** command to the current Inspection Plan.

Creating Location Dimensions

If you want to create a location dimension for any feature, you can use the **Location** icon.

- 1. Select the Location icon on the toolbar.
- 2. The IP Location Command dialog box appears.

IP Location Command 🔗 🗙
Label Loc1
Feature Pt1
Insert in Plan Plan 1
Select Tolerance Axis
🗌 Angle
🖬 X Axis 🗌 Length
🖬 Y Axis 🗌 Height
🖉 Z Axis 🗌 Polar Radius
Diameter Polar Angle
🗌 Radius 🛛 🖾 T Vector
Tolerance
Axis: X Axis
+ Tol 0
- Tol 0
Set Tolerance to ALL
Set Default Tolerance
OK OK Cancel

IP Location Command dialog box

- 3. If needed, type an ID for this location in the Label box.
- 4. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 5. Select the IP feature to be used for this IP Location from the model window or by selecting it from the feature tree. It will appear in the **Feature** box. Additionally, the appropriate default axes will be selected. For example, if an IP point is selected, then the **X**, **Y**, **Z**, and **T Vector** axes will be selected.
- 6. For each axis selected, type appropriate positive and negative tolerances. There is a different set of positive and negative tolerances for each axis. Select the needed **Axis** from the drop-down box and change the values in the **+ Tol** and **-Tol** boxes.
- 7. If the same tolerances are wanted for more than one axis, click the **Set Tolerance to ALL** button. This sets the specified tolerances for all selected axes.
- If more than one IP Location command will be created, then click the Set Default Tolerances button. This sets the default tolerances for all axes to the currently specified values. Next time a new IP Location is created, it will start out with the default tolerance values that were set.
- 9. Click **OK** to accept the current values and add the **IP Location** command to the current Inspection Plan.

Inserting Comments

Comments come in three types: Operator, Programmer, or Report. This allows you to insert a specific type of comment into your Inspection Plan, providing instructions to operators, programmer notes, or notes that will show up on your Inspection Plan reports.

- 1. Select the **Comment** icon on the toolbar.
- 2. The **IP Comment Command** dialog box appears.

IP Comm	ent Command	<u>? ×</u>
Label	C1	
Comment	This is a comment	
Insert in	Plan Plan 1	
Туре	Operator 💌	
		OK Cancel

IP Comment Command dialog box

- 3. If needed, type an ID for this comment in the **Label** box. The default is C1 meaning the first comment in the plan. Additional comments will be C2, C3, etc. Modify these comment labels as needed.
- 4. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- 5. Edit the comment in the **Comment** box.
- 6. Select the type of comment to create (Operator, Programmer, or Report) from the **Type** box.
 - Operator comments appear as message boxes whenever the resulting part program is executed. They are useful for giving instructions to the operator at the measuring machine.
 - Programmer comments will not be visible to the operator in the resulting part program. But if someone opens up the part program and looks at the code they will be able to see the programmer comments.
 - Report comments send the specified comments into the report that gets generated once the part program finishes execution.
- 7. Click **OK** to accept the current values and add the **IP Comment** command to the current Inspection Plan.

Constructing Features

If you want to construct features from other features, you can use the **Construction** icon.

- 1. Select the Construction Feature icon on the toolbar.
- 2. The IP Construction Feature Command dialog box appears.

PC-DMIS Inspection Planner

IP Construct	ion Feature Co <mark>? ×</mark>
Label	CF1
Insert in Plan	Plan 1
IP Features	Pt1 Pt2
	Remove Feature
Feature Type	Point
Operation	Mid Point
	OK Gancel

IP Construction Feature dialog box

- 3. If needed, type an ID for this constructed feature in the **Label** box.
- 4. Select the needed plan from the **Plans** section of the **InspectionPlanner** Node in the feature tree. The selected plan is displayed in the **Insert In Plan** box.
- Select the IP features to be included in this construction feature from the model window or by selecting them from the feature tree. As you select features, IP adds them to the IP Features list. To remove a feature from the list, select that feature in the list, and then click the Remove Feature button.
- 6. Select the feature type to construct from the **Feature Type** drop down list and select the type of operation to be performed for that feature from the **Operation** drop down list.

See "<u>Appendix A: Constructed Features</u>" for more information about the construction operations that can be performed and the related feature types that can be created.

7. Click **OK** and the constructed feature will be added to the Inspection Plan.

Adding an Existing Feature to the Current Plan

To add an existing CATIA V5 feature to the active Inspection Plan, follow these steps:

- 1. Select the **Feature** icon on the toolbar. No dialog box appears.
- 2. Select the IP feature to be added to the Inspection Plan from the model window, or select it from the feature tree.

Editing your Inspection Plan in CATIA 5

ー 首 InspectionPlanner 人 首 Plans 人 日 Plan 1	To edit commands of your Inspection Plan you have already created you will need to use the feature tree for CATIA 5. This will allow you to go back and make changes to the values of your Inspection Plan.
⊢ Ö Plan 2 ⊶ Ö Plan 3	You can also use the Reorder Commands button to change the order of the commands in your Inspection Plan.
	To Edit your Inspection Plan:
- # Edg1 - 1 Pin1 - 1 Cyl1	 Double-click on any of the features in the IP Features list, or Alignments, Translations, Rotations, Locations, Comments, or Constructions in the Plan list.
- 💽 Sph1 - 🖸 Cir1 - 🛄 Sl1	Note: You may also double-click on the feature label in the graphics display to edit the values.
- 🛄 si2 - 🏦 Pin2	 Edit values in the applicable dialog box to the needed values. For example, edit the nominal information in the Circle Feature dialog box for a Circle.
- 20 Ln2 - 20 Pt2 - 20 Pt3	 Click OK to save the changed values or click Cancel to abort any changes that have been made.
	 Click the Reorder Commands button to change the order of commands in your Inspection Plan. See the "Changing the order of the Items in a Plan" topic for more information.
PEALTRES	information. 5. To rename the plan, double-click the Plan name and change the name in the Plan dialog box. Click OK to save.
Edg1 Edg1 	 Click the Text Output button to save your changed Inspection Plan. See the "<u>Exporting a Plan to a File</u>" topic for more information.
- 💮 Sph1 - 🖸 Cir1	
- 🛄 511 - 🌅 512 - 🏦 Pin2	
-201 Ln2 -201 Pt2 -201 Pt3	
Pt4	

Using PC-DMIS Inspection Planner for SolidWorks

This topic describes how to install and use PC-DMIS Inspection Planner with SolidWorks. It shows how to perform various sub tasks needed to create an Inspection Plan that you can either store with your CAD data or export as a text file.

The **Inspection Planner** option must be enabled on your portlock to use the Inspection Planner capabilities for SolidWorks.

Installing Inspection Planner for SolidWorks

- Log on to the Wilcox ftp site: <u>ftp.wilcoxassoc.com</u>. Browse to the InspectionPlanner/SolidWorks directory. Enter the directory of the desired version and download the install executable, **Install_PCDMIS_xxx_IPSolidWorks.exe**, file to a specified directory on your hard drive.
- 2. Double-click on the downloaded .exe file to begin the installation of **IP** for **SolidWorks**
- The Setup program will then prompt you to select the location where to install PC-DMIS Inspection Planner for SolidWorks. The default directory might look something like this; C:\PCDMISW\InspectionPlanner\SolidWorks.
- 4. The Setup program will then copy files for **PC-DMIS Inspection Planner for SolidWorks** to this newly created directory.

The Setup program will verify that the needed file structure and files for SolidWorks are installed where you previously specified. An error will occur if the files do not exist.

To start the PC-DMIS Inspection Plan application

To start a PC-DMIS Inspection Plan session from within your SolidWorks session, follow this procedure:

- 1. Start SolidWorks.
- 2. Open the SolidWorks Add-Ins dialog box by selecting Tools | Add-Ins...
- 3. Ensure that the **PC-DMIS Inspection Planner** check box gets selected.
- 4. Click **OK** to activate Inspection Planner inside SolidWorks.

Add-Ins		? ×
 ✓ 3D control DrawCompare FeatureWorks MoldflowXpress ✓ PC-DMIS Inspection I PDMWorks 2004 	► Plann ▼	OK Cancel

SolidWorks Add-Ins dialog box.

5. There should now be an **Inspection Planner** menu option in the SolidWorks menu bar.

Sol 🕼	idWor	ks 2005	- ip_	block3.SL	DPP.T	
File E	dit Viev	v Insert	Tools	3Dcontrol (Inspection Planner	Window Help
	3 📙 🗟	S 18		9 - 64 - 1	RES	3 50 - TR 3

Inspection Planner in SolidWorks toolbar.

Once you have started the PC-DMIS Inspection Planner application, you may create, list, and edit IP features, commands, and Inspection Plans.

Inspection Planner Menu Items

Selecting the **Inspection Planner** menu in the SolidWorks menu bar displays the **Inspection Planner** sub-menus and menu items. These menu items contain the tools for creating, editing, exporting, and using Inspection Plans.

PC-DMIS Inspection Planner

Inspection Planner	Wind
New	
Delete	
Feature	•
Datum	
Alignment	•
GDT Selection	
Location	
Construction	
Comment	
Show Plan	
Export	
Customize Menu	,

Inspection Planner menus

Creating a New Inspection Plan

To create a new PC-DMIS Inspection Plan, follow this procedure:

- 1. Select New from the Inspection Planner menu.
- 2. IP displays a check mark in front of the **New** menu item indicating that an Inspection Plan exists in the SolidWorks part.



If a plan already exists in the SolidWorks part, you will be asked if you want to replace the existing plan.

Deleting the Inspection Plan

To delete the current Inspection Plan from the SolidWorks part:

- 1. Select **Delete** from the Inspection Planner menu.
- 2. IP deletes the current Inspection Plan.

Showing the current Inspection Plan

To display the current Inspection Plan in the SolidWorks part:

- 1. Select Show Plan in the Inspection Planner menu.
- 2. The Inspection Plan dialog box appears.

Inspection Plan				_ 🗆 🗙
FEAT/PLANE.F11,108. DATUM/F11.DAT(A);	1,1.0; 56623.0.0.20.826067.0.01.0 755872.1.06967713.0,0.0,0 9.1776546.824809;-1.0,0,0,	0,-1.0;		
3	Inseit Alter E	idi Delet	e Close	2

Show Inspection Plan dialog box

- 3. You can edit the Inspection Plan using this dialog box.
 - **Insert After** Select a line in the plan, and click the **Insert After** button. This sets the insertion point in the plan. IP inserts all new objects after this line.
 - Edit Select a line in the plan, and click the Edit button. IP displays the dialog box for that object, allowing you to edit its contents
 - **Delete** Select a line in the plan, and click the **Delete** button. IP deletes the selected line from the plan.
 - Close Selecting the Close button closes the Inspection Plan dialog box.

Exporting the current Plan to a File

To Export the current Inspection Plan for use within PC-DMIS, follow this procedure:

1. Select **Export** from the **Inspection Planner** menu. The **Save As** dialog box appears.

Save As			?)
Save in: 🔯	SolidWorks	• ÷ €	I 👉 💷 -
<mark>≥)</mark> old ■) ip_test1.i	p		
File name:	1		Save
Save as type:	IP Files (*.ip)	•	Cancel

Save As dialog box.

- 2. Browse to the location where you would like to save the file. Specify a name for the Inspection Planner file in the **File name** box.
- 3. Click **Save** to export the file. This text file can then be imported into PC-DMIS. See "Importing the Inspection Plan".

Creating Features

Once you have created a new Inspection Plan, you can create features for that Inspection Plan. To create features, use this general method:

- 1. From the **Inspection Planner** menu, select the **Feature** sub-menu, and then select the feature that you want to create. A dialog box, specific to the feature you selected, appears. Inspection Planner supports the following features:
 - Point
 - Edge Point
 - Line
 - Plane
 - <u>Circle</u>
 - Cylinder
 - Round Slot
 - Square Slot
 - <u>Sphere</u>

1	
Feature 🕨 🕨	Point
Datum	EdgePoint
Alignment 🕨 🕨	Line
GDT Selection	Plane
Location	Circle
Construction	Cylinder
Comment	Round Slot
Show Plan	Square Slot
Export	Sphere
	Customine Menu
Customize Menu	Customize Menu

Feature menu

- 2. Using the mouse, select the face, edge, or vertex from the CAD display that will be used for the feature. IP may ask you to select with the mouse again, depending on the type of feature you are defining and the CAD object first selected. The **Open Feature** dialog box will display the correct values provided from the CAD data. You can edit these values as needed.
- 3. Click the **OK** (the green check mark) button to accept your changes and create the feature. This feature will be added to the Inspection Planner tree as well as to the currently active plan.

V You must create an Inspection Plan before you can create any features.

The dialog box for each specific type of feature is explained below:

Creating a Point Feature

- 1. Select **Point** menu item from the **Feature** sub-menu.
- 2. The **IP Point** dialog box appears.
- 3. Indicate the location of the point feature by clicking on any surface. IP will put the XYZ coordinate and IJK vector information for the point into the dialog box.

Point In	nformation
Γx:	0.000000
ΓY:	0.000000
⊏ z:	0.000000
	Find
1:	0.000000
J :	0.000000
K:	1.000000
	Flip Vector
	Clear
Param	elers
ID :	F1

IP Point dialog box

- 4. Change the values for the **XYZ** coordinates and the **IJK** vector values as needed. If you change the values, then the values no longer reflect the model geometry. You must select the **Find** button to find the closest point on the geometry before you can create the point.
- 5. Clicking Flip Vector will reverse the direction of the vector.
- 6. Clicking **Clear** will clear the values from the dialog box.
- 7. Change the **ID** if needed.
- 8. Select the **Sample Hits** check box if you want samples hits taken during the measurement of this feature.
- 9. Click **OK** (green check mark) to accept the current values and add the point feature to the current Inspection Plan.

Creating a Line Feature

- 1. Select the Line menu item from the Feature sub-menu.
- 2. The **IP Line** dialog box appears.
- 3. Indicate the location of the start point of the line feature by clicking the first point on any surface. IP inserts that start point location into the dialog box.
- 4. Indicate the location of the end point of the line feature by clicking a second point on any surface. IP inserts that end point location into the dialog box.

	formation 4
~:	0.000000
Υ:	0.000000
z:	0.000000
End	Point
X:	0.000000
Y:	0.000000
z÷	0.000000
Sur	iace Vector
1:	0.000000
J:	0.000000
К:	1.000000
	Flip Vector
	Clear

IP Line dialog box

- 5. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 6. Selecting Flip Vector will reverse the direction of the vector.
- 7. Selecting **Clear** will clear the values from the dialog box.
- 8. Change the **ID** if needed.
- 9. Click **OK** (green check mark) to accept the current values and add the line feature to the current Inspection Plan.

Creating an Edge Point Feature

- 1. Select the **EdgePoint** menu item from the **Feature** sub-menu.
- 2. The IP Edge Point dialog box appears.
- Indicate the location of the edge point feature by clicking on any surface near an edge. The point will snap to the nearest edge of the surface. IP inserts the point's location into the dialog box.

E doe E	oint Information
	0.000000
Yo	
	0.000000
Z:	0.000000
1:	0.000000
J:	-1.000000
К:	0.000000
	Flip Vector
Nor	mal Vector
1:	0.000000
J:	0.000000
К:	1.000000
	Flip Vector
	Clear

IP Edge dialog box

- 4. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 5. Selecting **Flip Vector** will reverse the direction of the vector.
- 6. Selecting **Clear** will clear the values from the dialog box.
- 7. Change the **ID** if needed.
- 8. Click **OK** (green check mark) to accept the current values and add the edge point feature to the current Inspection Plan.

Creating a Plane Feature

- 1. Select **Plane** menu item from the **Feature** sub-menu.
- 2. The **IP Plane** dialog box appears.
- 3. Indicate the location of the plane feature by clicking any surface. IP inserts the plane's location and vector data into the dialog box.

Plane In	nformation .
	0.000000
Y:	0.000000
Ζ:	0.000000
- E	0.000000
J:	0.000000
κ:	1.000000
	Flip Vector
	Clear

IP Plane dialog box

- 4. Change the values for the **XYZ** coordinates and the **IJK** vector values as needed.
- 5. Clicking Flip Vector will reverse the direction of the vector.
- 6. Clicking **Clear** will clear the values from the dialog box.
- 7. Change the **ID** if needed.
- 8. Click **OK** (green check mark) to accept the current values and add the **Plane** feature to the current Inspection Plan.
Creating a Cylinder Feature

- 1. Select **Cylinder** menu item from the **Feature** sub-menu.
- 2. The IP Cylinder dialog box appears.
- 3. Indicate the location of the cylinder feature by clicking the cylindrical surface of a cylinder. IP inserts the cylinder's XYZ and IJK information into the dialog box.

ylinde	r Information
X:	0.000000
Y:	0.000000
Ζ:	0.000000
E	0.000000
J:	0.000000
Κ:	1.000000
	Flip Vector
Dia	meter: 0.000000
He	ight: 0
	Clear
aram	
ID :	F6

IP Cylinder dialog box

- 4. Change the values for the **XYZ** coordinates and the **IJK** vector values as needed.
- 5. Selecting Flip Vector will reverse the direction of the vector.
- 6. Specify the **Diameter** and **Height** of the cylinder.
- 7. Selecting **Clear** will clear the values from the dialog box.
- 8. Change the **ID** if needed.
- 9. Select either Hole or Stud to determine whether it's an internal or external cylinder.
- 10. Click **OK** (green check mark) to accept the current values and add the **Cylinder** feature to the current Inspection Plan.

Creating a Circle Feature

- 1. Select **Circle** menu item from the **Feature** sub-menu.
- 2. The IP Circle dialog box appears.
- 3. Indicate the location of the circle feature by clicking a circular edge or cylindrical surface of the circle feature. IP inserts the circle's XYZ center and IJK vector into the dialog box.

Circle I	nformation
X	0.000000
Υ:	0.000000
Z:	0.000000
E	0.000000
J:	0.000000
К:	1.000000
	Flip Vector
Dia	meter: 0.000000
	Clear
arame	eters -
ID :	F5

IP Circle dialog box

- 4. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 5. Selecting **Flip Vector** will reverse the direction of the vector.
- 6. Type the **Diameter** of the circle.
- 7. Selecting **Clear** will clear the values from the dialog box.
- 8. Change the **ID** if needed.
- 9. Select either Hole or Stud.
- 10. Click **OK** (green check mark) to accept the current values and add the **Circle** feature to the current Inspection Plan.

Creating a Sphere Feature

- 1. Select **Sphere** menu item from the **Feature** sub-menu.
- 2. The **IP Sphere** dialog box appears.
- 3. Indicate the location of the sphere by clicking a circular edge or spherical face of the sphere. IP calculates the sphere's location and vector from where you clicked.

	Information
×	0.000000
Υ:	0.000000
Z:	0.000000
I:	0.000000
J:	0.000000
κ:	1.000000
	Flip Vector
Dia	meter: 0.000000
	Clear
arame	elers
ID :	F9

IP Sphere dialog box

- 4. Change the values for the **XYZ** coordinates and the **IJK** vector values as needed.
- 5. Selecting **Flip Vector** will reverse the direction of the vector.
- 6. Type a **Diameter** for the sphere.
- 7. Selecting **Clear** will clear the values from the dialog box.
- 8. Change the **ID** if needed.
- 9. Select either **In** or **Out** to specify whether or not the feature is an internal or external sphere.
- 10. Click **OK** (green check mark) to accept the current values and add the **Sphere** feature to the current Inspection Plan.

Creating Round or Square Slot Features

- 1. Select either Round Slot or Square Slot from the Feature sub-menu.
- 2. The **IP Slot** dialog box appears. The selected slot type will be selected based on the menu item that was clicked. You can change the slot type inside the dialog box as well.
- 3. Indicate the location of the slot by selecting the face that the slot is cut out of. Select near the edge of the slot. IP will insert the center point and vector information into the dialog box.

	IP Slot
(
Slot Inf	ormation 🖌
Cen	ter Point
X:	0.000000
Υ:	0.000000
Z:	0.000000
Non	mal Vector
1:	0.000000
J :	0.000000
К:	1.000000
	Flip Vector
Orie	ntation Vector
1:	1.000000
J :	0.000000
к:	0.000000
	Flip Vector
Wid	th: 0.000000
Len	gth: 0.000000
	Round Slot
	C Square Slot
	Clear
Parame	ders 4
ID :	F7
	· Hole
	C Stud

IP Slot dialog box

- 4. Change the values for the **XYZ** coordinates and the **IJK** normal vector values as needed.
- 5. Change the values for the **IJK** orientation vector values as needed.
- 6. Selecting Flip Vector will reverse the direction of the normal or orientation vectors.
- 7. Specify the Width and Length of the slot.
- 8. Select either Round or Square Slot.

- 9. Selecting **Clear** will clear the values from the dialog box.
- 10. Change the ID if desired
- 11. Select either Hole or Stud.
- 12. Click **OK** (green check mark) to accept the current values and add the **Slot** feature to the current Inspection Plan.

Constructing Datum Features

If you want to construct datum features, you can use the Datum menu option,

- 1. Select **Datum** from the **Inspection Planner** menu.
- 2. The **IP Datum** feature dialog box appears.

IP Datum		×
ОК	Cancel	
Datum Letter : B		
F10 :Plane		

IP Datum feature dialog

- 3. Specify the datum by:
 - Selecting the datum from the graphic window, or...
 - Selecting the IP features to be included in this IP datum feature by selecting them from the feature list at the bottom of the dialog box.
- 4. Change the **Datum Letter** if needed.
- 5. Click **OK** to add the **Datum** feature to the Inspection Plan.

Creating Alignments

The **Alignment** sub-menu provides you with menu items to create, rotate, and translate alignments.

Alignment 🕨	New
GDT Selection	Rotate
Location	Translate
Construction	Customize Menu
Comment	Custonnize Mena
A l'ann an a m (an a m)	

Creating New Alignments

Once you have created your features, you can create or modify alignments.

- 1. Select **New** from the **Alignment** menu.
- 2. The **IP Alignment** dialog box appears.

P Alignm	nent 👱
OK	Cancel
Labet A	4
PRIMARY	
Feature :	F10 :Plane
Level To :	ZPLUS 💌
SECONDA	RY
Feature :	F11:DAT(A) :Plane
Rotate To	PUS -
About :	ZPLUS 💌
× ORIG:	F12:DAT(C) :Plane
Y ORIG:	F11:DAT(A) :Plane
Z ORIG:	F10 :Plane
Ţ	Clear
Datum / Fe	sature :
F10 :Plan F11:DAT(F12:DAT(e A) : Plane D) Plane

IP Alignment dialog box

- 3. If needed, type an ID for this alignment in the **Label** box.
- 4. In the **Primary** alignment section, indicate the axis you want to **Level to** for the primary alignment IP feature. Select the proper axis from the drop-down list. The default axis is **ZPLUS**.
- Select the primary alignment IP feature by selecting the proper feature in the Datum / Feature list. Click in the Primary Feature box, and then press your keyboard's Enter key.
- In the Secondary alignment section, indicate the axis to Rotate to and the axis to rotate About for the secondary alignment IP feature. Select the proper axes in the drop-down lists.
- 7. Select the secondary alignment IP Feature by selecting the proper feature in the Datum / Feature list. Click in the Secondary Feature box then press your keyboard's Enter key.
- 8. As you select the primary and secondary IP features, they are also set, as appropriate, in the X, Y, and Z Origin boxes.

- 9. Selecting Clear will clear the values from the dialog box.
- 10. Any of the IP features can be changed by selecting the proper feature in the **Datum / Feature** list. Simply click in the **Feature** box then press the **Enter** key.
- 11. Click **OK** to accept the current values and add the **IP Alignment** command to the current Inspection Plan.

Rotating Alignments

You can rotate your Inspection Plan's current alignment by a specified angle.

- 1. Select Rotate from the Alignment menu.
- 2. The Rotate Alignment dialog box appears.

Rotate Alig	nment	×
OK	Cancel	
Label: A2		
Angle: 0		
C Rotate	e about X Axis	
C Rotate	e about Y Axis	
Rotate	e about Z Axis	

Rotate Alignment dialog box

- 3. If needed, type an ID for the alignment you want to rotate in the Label box.
- 4. Type the angle of the rotation in the **Angle** box.
- 5. Select the axis (X, Y, or Z) you want to rotate about in the **Axis** box.
- 6. Click **OK** to accept the current values and add the **Rotate Alignment** command to the current Inspection Plan.

Translating Alignments

You can translate (or move) your Inspection Plan's current alignment by an offset distance.

- 1. Select **Translation** from the **Alignment** menu.
- 2. The Translate Alignment dialog box appears.

Translate Ali	gnment	×
OK	Cancel	
Label: A3 Distance: 0		
 Move in the Move in the Move in the 	ne Y direction	

Translate Alignment dialog box

- 3. If needed, type an ID for the alignment you want to translate in the Label box.
- 4. Type the values for the translation along the X, Y, or Z axes in the **Distance** box.
- 5. Specify which axes direction to move along by selecting **Move in the X direction**, **Move in the Y direction**, or **Move in the Z direction**.
- 6. Click **OK** to accept the current values and add the **Translate Alignment** command to the current Inspection Plan's alignment.

Constructing GD&T Features

If you want to construct features from tolerances (GD&T), you can use the **GD&T Selection** menu option,

- 1. Select **GD&T** Selection from the **Inspection Planner** menu.
- 2. Select a **GD&T** feature from the graphic window.
- 3. The **IP GD&T** dialog box appears. The feature for the GD&T feature will be highlighted in the feature list.

IP GD&T		×
OK	Cancel	
Label: D1 Features:		
F10 :Plane F11 :Plane F12 :Plane F13 :1 Circle		

IP GD&T dialog box

- 4. If needed, type an ID for this alignment in the **Label** box.
- 5. You may change the associated feature by selecting a new feature from the Features list.
- 6. Click **OK** to add the GD&T constructed feature to the Inspection Plan.

Creating Location Dimensions

If you want to create a location dimension for a feature, you can use the **Location** menu option.

- 1. Select Location from the Inspection Planner menu.
- 2. The IP Location dialog box appears.

PC-DMIS Inspection Planner

	oca	tion				>
	OK			Ca	ncel	
	Labe	e	D2	_	_	-
Fea	ture :					
F11 F12) :Pla :Pla :Pla :Pla :Cin	ne				
1000	elect 1	Folera	nce	Axis Angl		
F	X Au Y Au Z Au Dian Rad	ais ais neter		Leng Heig Pola Pola T ve	ht r Rad r Angi	ius le
LLLL	Y As Z As Dian	ds ds neter lius		Heig Pola Pola	ht r Rad r Angi	ius le
	Y Au Z Au Dian Rad	ais ais neter lius ce		Heig Pola Pola	ht r Rad r Angi	ius le
	Y Au Z Au Dian Rad oleran	ais ais neter lius ce		Heig Pola Pola	ht r Rad r Angi	ius le
	Y Au Z Au Dian Rad deran is : fol :	ás ás neter itus ce ALL		Heig Pola Pola	ht r Rad r Angi	ius le
	Y As Z As Dian Rad seran is : fol :	ás neter ius ALL 0.000		Heig Pola Pola T ve	ht r Rad r Angl ctor	ius le

IP Location dialog box

- 3. Select the IP feature to be used for this IP Location from the model window or by selecting it from the feature tree. IP adds it to the **Feature** box.
- 4. When you select the IP feature, IP uses the appropriate default axes. For example, if you select IP point, then the IP selects the **X**, **Y**, **Z**, and **T Vector** axes.
- 5. For each axis selected, type appropriate positive and negative tolerances. There is a different set of positive and negative tolerances for each axis. Select the needed **Axis** from the drop-down box and change the values in the **+ Tol** and **-Tol** boxes.
- 6. If the same tolerances are wanted for more than one axis, click the **Set Tolerance to ALL** button. This sets the specified tolerances for all selected axes.
- 7. If more than one IP Location command will be created, then click the Set Default Tolerances button. This sets the default tolerances for all axes to the currently specified values. Next time a new IP Location is created, it will start out with the default tolerance values that were set.
- 8. Click **OK** to accept the current values and add the **IP Location** command to the current Inspection Plan.

Constructing Features

If you want to construct features from other features, you can use the **Construction menu** option.

- 1. Select **Construction** from the **Inspection Planner** menu.
- 2. The **Constructed Feature** dialog box appears.

OK Label: F1	_	ncel
Feature Typ		<u>•</u>
Operation	INTER INTER CAST DROP PROJ	•
Feature :		
F10 :Plan F11 :Plan F12 :Plan	8	

Constructed Feature dialog box

- 3. Select the IP features to be included in this IP Construction Feature by selecting them from the **Feature** list.
- 4. Select the feature type to construct from the **Feature Type** drop down list and select the type of operation to be performed for that feature from the **Operation** drop down list.

See "<u>Appendix A: Constructed Features</u>" for more information about the construction operations that can be performed and the related feature types that can be created.

5. Click **OK** and the **Constructed feature** will be added to the Inspection Plan.

Inserting Comments

Comments come in three types: Operator, Programmer, or Report. This allows you to insert a specific type of comment into your Inspection Plan, providing instructions to operators, programmer notes, or notes that will show up on your Inspection Plan reports.

- 1. Select **Comment** from the **Inspection Planner** menu
- 2. The IP Comment dialog box appears.

OK	Cancel	Operator	
		([©] Operator ⊂ Report ⊂ Programmer	
		C Programmer	

IP Comment dialog box

- 3. Edit the comment in the **Comment** box.
- 4. Select the type of comment to create: **Operator**, **Report**, **or Programmer**.
 - Operator comments appear as message boxes whenever the resulting part program is executed. They are useful for giving instructions to the operator at the measuring machine.
 - Programmer comments will not be visible to the operator in the resulting part program. But if someone opens up the part program and looks at the code they will be able to see the programmer comments.
 - Report comments send the specified comments into the report that gets generated once the part program finishes execution.
- 5. Click **OK** to accept the current values and add the **IP Comment** command to the current Inspection Plan.

Using PC-DMIS Inspection Planner for Unigraphics

This topic describes how to install and use PC-DMIS Inspection Planner within Unigraphics. IP allows you to perform various sub tasks needed to create an Inspection Plan that you can either store with your CAD data or export as a text file.

The **Inspection Planner** option must be enabled on your portlock to use the Inspection Planner capabilities for Unigraphics.

To install the PC-DMIS Inspection Planner

To install the PC-DMIS Inspection Planner for access from within the Unigraphics CAD system (NX 2.0 and later), follow this procedure:

- Log on to the Wilcox ftp site: <u>ftp.wilcoxassoc.com</u>. Browse to the /InspectionPlanner/Unigraphics/ directory. Enter the directory of the desired version and download the install executable, **Install_PCDMIS_370_IPUnigraphics.exe**, file to a specified directory on your hard drive.
- 2. Double-click on the **Install_PCDMIS_370_IPUnigraphics.exe** file to begin the installation of IP for Unigraphics. Follow the instructions to install IP for Unigraphics.

The Setup program will verify the proper installation of Unigraphics on your system. It will fail if it does not find the Unigraphics installation.

3. Start Unigraphics and you should see **Inspection Planner...** in the **Application** menu.

The PC-DMIS Inspection Plan application will now be available from within your Unigraphics sessions.

To start the PC-DMIS Inspection Plan application

To start a PC-DMIS Inspection Plan session from within your Unigraphics session, follow this procedure:

- 1. Start Unigraphics software.
- 2. Open your part file.
- 3. Switch to the Inspection Planner application by selecting **Application | Inspection Planner...**



Start Inspection Planner Application

4. Inspection Planner launches and the Inspection Planner toolbar appears.



Once the PC-DMIS Inspection Planner application launches you may create, list, and edit Inspection Plans.

Except for the **New Plan** icon, the **Inspection Plan** menu and the other toolbar icons will remain grayed out until you create an Inspection Plan.

To Create a New PC-DMIS Inspection Plan

To create a PC-DMIS Inspection Plan, follow this procedure:

1. Start a new Inspection Plan by selecting the **Inspection Planner | New** menu option or select the **New Inspection Plan** icon in the toolbar. This displays the **IP Name** dialog box.

🐉 IP Name	×		
New Inspection Plan Name			
Inspection Plan			
ОК	Cancel		

IP Name dialog box

2. Type the name for the new Inspection Plan and Click **OK**. This creates a new Inspection Plan and adds the default header information to it. The rest of the **Inspection Plan** menu and toolbar icons become available for selection.



If you ever want to start over, select the **Inspection Planner | Delete** menu option to delete the current Inspection Plan.

Creating Features

Once you have created a new Inspection Plan, you can create features for that plan. To create features, use this general method:

- 1. From the **Inspection Planner** menu, select the **Feature** sub-menu, and then select the feature that you want to create. A dialog box, specific to the feature you selected, appears. Inspection Planner supports the following features:
 - Point
 - Line
 - Edge Point
 - Plane
 - <u>Cylinder</u>
 - Sphere
 - <u>Circle</u>
 - Round Slot
 - Square Slot
- 2. Using the mouse, select the face, edge, or vertex from the CAD display that will be used for the feature. IP may ask you to select with the mouse again, depending on the type of feature you are defining and the CAD object first selected. The **Open Feature** dialog box will display the correct values provided from the CAD data. You can edit these values as needed.
- 3. Click the **OK** button to accept your changes and create the feature in the Inspection Plan.

The dialog box for each specific type of feature is explained below:

Creating a Point Feature

- 1. Select Inspection Planner | Feature | Point or the Point icon on the toolbar.
- Indicate the location of the point feature by clicking on any surface. The IP Point feature dialog box appears. IP will put the XYZ coordinate and IJK vector information for the point into the dialog box.

NP Point	×
Feature ID :	21
x: [96.0499
Y: [96.1582
z: [22.0000
	Show Point
i: [0.0000
ı: [0.000
к: Г	1.0000
1	Flip Vector
Γ	Sample Hits
	ong given Axis
│ × Axis	
T Y Axis	
C Axis	
	Find
Γ	OK Cancel

IP Point dialog box

- 3. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 4. Click the **Show Point** button to display the point 3D CAD view.
- 5. Click the Flip Vector button to flip the currently assigned vector.
- 6. Click the **Sample Hits** option if you want sample hits to be taken for the point. These hits are taken around the nominal point.
- 7. Select the check boxes next to the X, Y, and Z Axis options to find values along these axes.
- 8. Click **OK** to accept the current values and add the point feature to the current Inspection Plan.

Creating a Line Feature

- 1. Select Inspection Planner | Feature | Line or the Line icon on the toolbar.
- 2. Indicate the location of the start point of the line feature by clicking the first point on any surface. IP inserts that start point location into the dialog box.
- 3. Indicate the location of the end point of the line feature by clicking a second point on any surface. IP inserts that end point location into the dialog box.

🐉 IP Lin	е	×
Feature ID	: F2	
Start Point		
x:		84.3820
Υ:		98.4131
z :		22.0000
End Point		
X:		75.5873
Υ:		78.9419
z :		22.0000
	Show Point	s
Surface Ve	ctor	
B		0.0000
J:		0.0000
к:		1.0000
	ок	Cancel

IP Line dialog box

- 4. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 5. Click the **Show Point** button to display the point 3D CAD view.
- 6. Click **OK** to accept the current values and add the line feature to the current Inspection Plan.

Creating an Edge Point Feature

- 1. Select Inspection Planner | Feature | Edge Point or the Edge Point icon on the toolbar.
- Indicate the location of the edge point feature by clicking on any surface near an edge. The point will snap to the nearest edge of the surface. The IP Edge Point dialog box appears containing the point's location.

🚧 IP Edg	e Point	×
Feature ID :	F2	
X:	1	56.0342
Υ:		0.0000
z :		22.0000
	Show Point	
Edge Vecto	r	
t:		0.0000
j:		-1.0000
к:		0.0000
Normal Vec	tor	
1:		0.0000
J:		0.0000
к:		1.0000
	ОК	Cancel

- IP Edge Point dialog box
- 3. Change the values for the **XYZ** coordinates and the **IJK** vector values as needed.
- 4. Click the **Show Point** button to display the point 3D CAD view.
- 5. Click **OK** to accept the current values and add the edge point feature to the current Inspection Plan.

Creating a Plane Feature

- 1. Select Inspection Planner | Feature | Plane or the Plane icon on the toolbar.
- 2. Indicate the location of the plane feature by clicking any face. **The IP Plane** dialog box appears containing the plane's location and vector data.

Feature ID :	F2
x:	11.1980
Y:	11.4448
z :	0.0000
	Show Vector
I:	0.0000
J:	0.000
к:	1.0000
	OK Cancel

IP Plane dialog box

- 3. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 4. Click the **Show Vector** button to display the vector 3D CAD view.
- 5. Click **OK** to accept the current values and add the plane feature to the current Inspection Plan.

Creating a Cylinder Feature

- 1. Select Inspection Planner | Feature | Cylinder or the Cylinder icon on the toolbar.
- Indicate the location of the cylinder feature by clicking the circular edge or cylindrical surface of the cylinder. The IP Cylinder dialog box appears containing the cylinder's XYZ and IJK information.

🕺 IP Cylir	ider 🔰
Feature ID :	F2
Center Point	
×:	154.5835
Υ:	80.4055
Z :	22.0000
	Show Feature
Axis	
E.	0.0000
J:	0.0000
к:	1.0000
Diameter :	15.0000
Height :	1.0000
	ype Hole C Stud
	OK Cancel

IP Cylinder dialog box

- 3. Change the values for the XYZ coordinates and the IJK vector values as needed.
- 4. Click the **Show Feature** button to display the Cylinder 3D CAD view.
- 5. Type the **Diameter** and **Height** of the cylinder.
- 6. Select the Type of feature: **Hole** or **Stud**.
- 7. Click **OK** to accept the current values and add the cylinder feature to the current Inspection Plan.

Creating a Sphere Feature

- 1. Select Inspection Planner | Feature | Sphere or the Sphere icon on the toolbar.
- Indicate the location of the sphere by clicking a circular edge or spherical face of the sphere. The IP Sphere dialog box appears containing the sphere's location and vector information.

3 IP Sphere	×
Feature ID :	
x:	168.6780
Y:	45.6600
z:	22.0000
Show	Sphere
I:	0.0482
J:	-0.4214
к:	0.9055
Diameter :	12.7000
C IN @ OUT	
	OK Cancel

IP Sphere dialog box

- 3. Change the values for the **XYZ** coordinates and the **IJK** vector values as needed.
- 4. Click the Show Sphere button to display the Sphere 3D CAD view.
- 5. Type a **Diameter** for the sphere.
- 6. Select either **In** or **Out** to specify whether or not the feature is an internal or external sphere
- 7. Click **OK** to accept the current values and add the sphere feature to the current Inspection Plan.

Creating a Circle Feature

- 1. Select Inspection Planner | Feature | Circle or the Circle icon on the toolbar.
- Indicate the location of the circle feature by selecting a circular edge or cylindrical surface of the circle feature. The IP Circle dialog box appears containing the circle's XYZ center and IJK vector.

SIP Cirlc	e)	
Feature ID :		
Center Point		
x:	154.5835	
Υ:	80.4055	
z :	22.0000	
	Show Circle	
Axis		
t:	0.0000	
j:	0.0000	
К:	1.0000	
Diameter :	15.0000	
	ype Hole C Stud	
	OK Cancel	

- 3. Change the values for the **XYZ** coordinates and the **IJK** vector values as needed.
- Click the Show Circle button to display the Circle 3D CAD view.
- 5. Type the **Diameter** of the circle.
- 6. Select either **Hole** or **Stud** to specify whether or not the feature is an internal or external circle.
- 7. Click **OK** to accept the current values and add the circle feature to the current Inspection Plan.

Creating Round Slot or Square Slot Features

- 1. Select the **Inspection Planner | Feature | Round Slot** or **Square Slot** menu items. Or select the **Round** or **Square Slot** icon on the toolbar.
- 2. Indicate the location of the round slot by selecting a face or edge of the round slot feature.
- 3. IP may ask you to select the opposite edge or face of the round slot.
- 4. The **IP Slot** dialog box appears.

Slot Slot	×		
Feature ID :	eature ID : F3		
Center Point			
X:	191.1780		
Y:	73.0000		
z :	22.0000		
S	how Location		
Normal Vector	r		
t:	0.0000		
J:	0.0000		
К:	1.0000		
Orientation Ve	ctor		
t:	1.0000		
J:	0.0000		
к;	0.0000		
Width :	7.0000		
Length :	47.0000		
6	Round Slot		
0	Square Slot		
	Hole		
0	Stud		
1	OK Cancel		

IP Slot dialog box

- 5. Change the values for the **XYZ** coordinates and the **IJK** vector values as needed.
- 6. Click the Show Location button to show the location of the slot 3D CAD view.
- 7. Type the **Width** and **Length** of the slot.
- 8. Select either Round or Square Slot.
- 9. Select either **Hole** or **Stud** to determine whether the slot is an internal or external slot.
- 10. Click **OK** to accept the current values and add the slot feature to the current Inspection Plan.

Creating Commands for Datum

If your CAD has datum items defined, you can create Inspection Planner commands for them.

- 1. Select Inspection Planner | Datum menu or the Datum icon.
- 2. The Select Datum Feature dialog box appears.

🎉 Select E _{Name}	atum Fea	ature 📩
ОК	Back	Cancel

Select Datum Feature dialog box

- 3. Select the appropriate datum symbol from the 3D CAD view.
- 4. The IP Datum definition dialog box appears.

🖏 IP Datum		×
Datum Letter :		A
Features :		
F2 :Plane F3 :Plane F6 :Plane		
FO Plane		
-		
	ОК	Cancel

IP Datum dialog box

IP highlights the feature associated with the datum in both the 3D CAD view and the **Features** list in the **IP Datum** dialog box.

- 5. If you want to change the **Datum Letter**, select the datum letter in the dialog box and enter the new letter.
- 6. If you want to change the feature associated with the datum, select the new feature in the **Features** list. The newly selected feature will be highlighted in the 3D CAD view.

This only changes the feature associated with the datum for the Inspection Plan. It does not affect the datum's association in the CAD file in any way.

7. Click **OK** to add the datum to the Inspection Plan. The associated feature will also be added to the Inspection Plan if it was not already in the plan.

Creating Alignments

Once you have created your features and datum commands, you can create or modify alignments.

1. Select the **Inspection Planner | Alignment | New** menu option, or the **New Alignment** icon on the toolbar. The **IP Align** dialog box appears.

🚧 IP Aligi	-	×
Label :	A6	
PRIMARY		
Feature ID :	F2	
Level To :		ZPLUS 💌
SECONDARY	0	
Feature ID :	F3	
Rotate To :		XPLUS 💌
About:		ZAXIS 💌
X Origin :	F7	
Y Origin :	F3	
Z Origin :	F2	
Feature List	t	
F2 :Plane		
F3 :Plane F7 :Plane		
13		
	ОК	Cancel

- IP Align dialog box
- 2. If needed, type an ID for this alignment in the **Label** box.
- 3. From the **Feature List**, select the feature required to **Level To**. Click in the **PRIMARY Feature ID** box. Press **Enter** and IP adds the highlighted feature to the **Feature ID** box. Choose the needed axis from the **Level To** box
- From the Feature List, select the feature required to Rotate To. Click in the SECONDARY Feature ID box. Press Enter and IP adds the highlighted feature to the Feature ID box. Choose the needed axes from the Rotate To and About boxes.
- From the Feature List, select the feature required to establish an Origin. Click in the (X, Y, or Z) Origin box. Press Enter and IP adds the highlighted feature to the specified Origin box. Continue the process until each of the XYZ boxes are filled with the needed features.
- 6. Click **OK** and the specified **Alignment** will be entered into the current Inspection Plan.

Translating Alignments

You can translate (or move) your Inspection Plan's current alignment by an offset distance.

1. Select the **Inspection Planner | Alignment | Translate** menu option, or the **Translate Alignment** icon on the toolbar. The **IP Translate** dialog b₀x appears.

🖏 IP Trans	late	×
Label :	A9	
Distance :		0.0000
Move along ax	(is :	XAXIS 💌
	ок	Cancel

IP Translate dialog box

- 2. Type the required distance to move the alignment in the **Distance** box, and select the axis from the **Move along axis** box.
- 3. Click **OK** and the specified alignment will be translated to the distance specified along the chosen axis and added to the Inspection Plan.

Rotating Alignments

You can rotate your Inspection Plan's current alignment by a specified angle.

1. Select the **Inspection Planner | Alignment | Rotate** menu option, or the **Rotate Alignment** icon on the toolbar. The **IP Rotate** dialog box appears.

🐉 IP Rotat	te	×
Label :	A10	
Angle :		0.0000
Rotate About	::	ZAXIS 💌
	ОК	Cancel

IP Rotate dialog box

- 2. Type the required angle (in degrees) in the **Angle** box, and select the axis from the **Rotate About** box.
- 3. Click OK, and IP will rotate the Inspection Plan's alignment about the specified axis

Creating Tolerances

The **Tolerance** menu option allows you to select GD&T Feature Control Frame symbols to create IP tolerances.

- 1. Select **Inspection Planner | GDT Selection** from the menu.
- 2. The Select Tolerance Feature dialog box appears.

祸 Select G	GDT Tole	rance 🗙
Name		
·		
OK	Back	Cancel

Select GDT Tolerance Feature dialog box

- 3. Select the appropriate Feature Control Frame symbol from the 3D CAD view.
- 4. The **IP GD&T** definition dialog box appears.

将 IP GD&T	×
Label :	D1
Features :	
F1:DAT(A) :Plane F2:DAT(B) :Plane F3:DAT(C) :Plane	
F4 :Cylinder F5 :Cylinder	
	OK Cancel

IP GD&T dialog box

IP highlights the feature(s) associated with the tolerance in both the 3D CAD view and the feature list in the **IP GD&T** dialog box.

- 5. If you want to change the **Label**, select the label in the dialog box and type a new letter.
- If you want to change the feature(s) associated with the tolerance, select the new feature(s) in the Features list. The newly selected feature(s) will be highlighted in the 3D CAD view.

This only changes the feature(s) associated with the tolerance for the Inspection Plan only. It does not effect tolerance's association in the CAD file in any way.

7. Click **OK** to add the Tolerance Feature Control Frame to the Inspection Plan. IP also adds the associated feature(s) to the Inspection Plan if not already in the plan.

Creating Location Dimensions

If you want to create a location dimension for any features, you can use the **Location** menu option.

1. Select **Inspection Planner | Location** from the menu or the **Location** icon from the toolbar. The **IP Feature Location** dialog box appears showing a list of all the IP features.

IP Featu			
Label :	D2		
Feature List :			
F2 :Plane F3 :Plane F7 :Plane			
-Select Tolera		- Angle	
T XAxis		Leng	
T YAxis		Heigh	
ZAXIS	1	Polar	
Diameter	1		Radius
Radius		TVec	
Tolerance			
Axis :	P	ALL	-
Dive Telesco	ce :	0.	0000
Plus Tolerand			
Minus Tolera	nce :	0.	0000
Minus Tolera	ince : Tolerance	1	0000
Minus Tolera Set 1		to ALL	0000

IP Feature Location dialog box

2. Select the feature from the List or select the feature's label from the 3D CAD view. It will be added to the **Feature List** box.

- 3. When the IP feature is selected from the **Feature List**, the appropriate default axes will be selected. For example, if an IP point is selected, then the **X**, **Y**, **Z**, and **T Vector** axes will be selected.
- 4. For each axis selected, type appropriate positive and negative tolerances. There is a different set of positive and negative tolerances for each axis. Select the needed **Axis** from the drop-down box and change the values in the **Plus Tolerance** and **Minus Tolerance** boxes.
- 5. If the same tolerances are wanted for more than one axis, click the **Set Tolerance to ALL** button. This sets the specified tolerances for all selected axes.
- If more than one IP Location command will be created, click the Set Default Tolerances button. This sets the default tolerances for all axes to the currently specified values. Next time a new IP Location is created, it will start out with the default tolerance values that were set.
- 7. Click **OK** to accept the current values or changes that have been made.

Constructing Features

If you want to construct features from other features, you can use the **Construction** option.

1. Select the **Inspection Planner | Construction** menu option or **Construction** icon in the toolbar. The **IP Feature Construction** dialog box appears letting you construct the desired feature from the list of features in the current Inspection Plan.

Feature Type : Operation :	Point •
Feature List :	
F2 :Plane F3 :Plane F7 :Plane	
	K Cancel

IP Feature Construction dialog

- 2. Select the features that are needed for the construction from the Feature List box.
- 3. Select the Feature type to construct from the **Feature Type** drop down list and select the type of operation to be performed for that feature from the **Operation** drop down list.

See "<u>Appendix A: Constructed Features</u>" for more information about the construction operations that can be performed and the related feature types that can be created.

4. Click **OK** and the **Constructed** feature will be added to the Inspection Plan.

Inserting Comments

Comments come in three types: Operator, Programmer, or Report. This allows you to insert a specific type of comment into your Inspection Plan, providing instructions to operators, programmer notes, or notes that will show up on your Inspection Plan reports.

If you want to insert comments into the Inspection Plan, select the **Inspection Planner** | **Comment** menu option or **Comment** icon in the toolbar. A **Comment** dialog box appears.

2, Comm	ent	×
	Type © Operator C Report C Programmer	
Comment		
		OK Apply Cancel

Comment dialog box

Use the **Comment** dialog box to select the type of comment (Operator, Report, or Programmer), type the comment, and click **OK** to insert it into the Inspection Plan.

- Operator comments appear as message boxes whenever the resulting part program is executed. They are useful for giving instructions to the operator at the measuring machine.
- Programmer comments will not be visible to the operator in the resulting part program. But if someone opens up the part program and looks at the code they will be able to see the programmer comments.
- Report comments send the specified comments into the report that gets generated once the part program finishes execution.

Displaying the Inspection Plan

At any time you can display the entire Inspection Plan. To do this, select the **Inspection Planner** | **Show Plan** menu option. Your CAD package will display a dialog showing the Inspection Plan.

nspection Plan			
- PLAN: Inspection Plan 1 PCDP /(Inspection Plan 1), 1.0; UNITS /MM; FEAT / PLANE, F1, 9.642112, 7.620668,0.0,0.0,0.0,0.1,0; FEAT / PLANE, F2, 42, 975569,0.0,2, 433856,0,0,-1,0,0,0; FEAT / PLANE, F3,0.0,26,21247,-9.731587,-1,0,0,0,0; ALICNIA, 12PLUS, F1, 2PLUS, F2, VORIG, F3, YORH; FEAT / CIRCLE, F4, 124, 178,50,0,22,0,0,0,0,0,1,0,60,5; FEAT / CIRCLE, F4, 124, 178,583592,80,405552,22,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,1,0,1,0,1,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,1,0,1,0,1,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0,1,0,1,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0,22,0,0,0,0; FEAT / RDSLOT, F6, 191, 178,73,0; FEAT / RDSLOT, F6, 191, 17	0; 0; C,F2,ZORIG,F1; INNER; (0.0,1.0,15.0,1.0,INNER; 0.0,0.0,7.0,47.0,INNER;		
FEAT/SCSLOT/F7.69.865553.23.334524.22.00.0.0 - Features FEAT/PLANE,F1,9.642112,7.620668,0.0,0.0,0,0,1.0; FEAT/PLANE,F2,42.975569,0.0,2.433856,0.0,-1.0,0. FEAT/PLANE,F3,0.0,26.21247,-9.731587,-1.0,0.0,0. FEAT/CIRCLE,F4,124.178,550,22.0,0.0,0.0,0.1,0,60 FEAT/CIRCLE,F4,124.178,5592,60.405592,22.0,0.0,0 FEAT/CUNDER,F5,154.565592,60.405592,22.0,0 FEAT/CLUDER,F5,154.565592,30.435592,20,0,0,0,1.0,1.0; FEAT/SCSLOT,F6,191.178,73.0,22.0,0.0,0,0,1.0,1.0; FEAT/SCSLOT,F7,69.869553,23.334524,22.0,0,0,0	0; 0; INNER; 1,0.0,1.0,15.0,1.0,INNER; 0.0,0.0,7.0,47.0,INNER;		
	Insert After	Edit	Delete

Inspection Plan display dialog box

The statements include:

- o Header
- o Comments
- o Measured features
- o Datum features
- o Dimensions
- o Alignments
- o Rules
- o Report options
- You can edit any command by selecting the command line and clicking the **Edit** button in the display dialog
- You can delete any command by selecting the command line and clicking the **Delete** button in the display dialog.
- You can set the insert position by selecting the command line and clicking the **Insert After** button in the display dialog. Any new commands will get inserted at that point.
- You can keep this plan open during the entire planning process.

Exporting Your Inspection Plan

The **Inspection Planner | Export** menu option, or the **Export** icon on the toolbar, allows you to specify a text file to which IP will save the current Inspection Plan. You can import this text file into PC-DMIS. See "Importing the Inspection Plan".

Using Inspection Planner within PC-DMIS

The following topics describe how to use the new functionality added to PC-DMIS for Windows to automatically create a part program from your Inspection Plan. To create your part program you need to do the following:

- Import the Inspection Plan you exported from your CAD package.
- Perform an optimization step on the imported plan,
- Ensure that the probe won't collide with the part by inserting proper move commands.

Once you have completed these simple tasks, you can then execute your imported inspection plan as a newly created PC-DMIS part program.

If you have problems using the Inspection Planner commands inside PC-DMIS, ensure that there is an *InsPlan.dll* file located in the directory where you installed PC-DMIS.

Inspection Planner Default File (IPD)

You must have an Inspection Planner Default file, or (IPD) to import an Inspection Plan into PC-DMIS. The "<u>Creating and Modifying an Inspection Planner Default (IPD) file</u>" provides more information on this file.

The **IP Measure** option must be enabled on your portlock to use the Inspection Planner capabilities that are discussed in this section.

Importing the Inspection Plan

You can import the Inspection Plan and any rules by either importing a CAD file that has the Inspection Plan tied to it, or by importing a previously exported Inspection Plan.

To import the Inspection Plan tied to a CAD model:

- 1. Select File | Import and then select the menu item to import that CAD data.
- 2. Follow any on-screen instructions.

For specifics on importing CAD data, see the "Using Advanced File Options" chapter in the main PC-DMIS manual.

To import the textual, exported Inspection Plan:

1. Select **File | Import | Inspection Plan**. An **Open** dialog box appears letting you select a file with an ".IP" filename extension.

n						1
Look in:	PCDMISW		-	+ 🗉 (* 🖽 •	
Pecard Decktop y Documente	Backup AIMS Answer Works AscImportAil Costa dd Dotabase Witer English Ideas InspectionPlan Jerry Najor Models ConeLIFiles Profutorial reporting	Vision Tutonial d Wizards				
Hy Network	File pane:	SW.IP		_	•	Inpot
Places	Files of type:	Inspection Plan Files (".IP)			•	Cance

- 2. Browse to the directory containing your Inspection Plan.
- 3. Select the Inspection Plan, and click Import.
- 4. Follow any on-screen instructions.
 - Select the **IPD** file that will be applied to the imported Inspection Plan if you have not previously selected it. See the "<u>Creating and Modifying an Inspection Planner Default</u> (<u>IPD) file</u>" topic for more information.
 - If the insertion point is not at the end of the part program, you will be prompted to move the cursor to the end of the part program before continuing.
 - Specify the Optimize Path options and click OK, or click Skip to ignore this step. See the "Performing the Path Optimization" topic for more information. Review the "Path Optimization Summary" and click OK.
 - Specify the options for "<u>Automatically Inserting Move Commands</u>" and click **OK** to complete this process or click **Cancel** to skip this step.

Your imported Inspection Plan will be proceeded by a start comment that provides basic information for the imported Inspection Plan (date/time, IP file name with path, IPD file name and path). An end comment is also added to indicate the end of the translated Inspection Plan.

Performing the Path Optimization

Once PC-DMIS finishes importing your inspection plan, you will see that the PC-DMIS edit window contains the commands needed to measure the desired features. Next, you need to optimize the order PC-DMIS takes to measure the features and what tip angles to use and when. This is called a "path optimization".

To perform a path optimization:

1. Select Edit | Optimize Path. the Optimize Path dialog box appears.

ptimize Path	×
Feature Range	
All Features	
C Selected Features	
Starting Feature:	
1	-
- Dimensions	
Insert at end	
C Insert as soon as po	ssible
Tip Changes	
🔽 Add Tip Changes	
Only Defined Tips	
Minimize Number	Second Second
Ask if can't find T	194 (AB196)
Conical Range of Tip Sha	
(cone half angle in de	22222022
5	
Sort penalty in seconds fo	r:
MIP/MIH	10
	10
PH9/PH10	3
PH9/PH10 PHS WRIST	3
	3
	3
	3
	3
PHS WRIST	3
PHS WRIST	3
PHS WRIST	3

Optimize Path dialog box

 Determine what features you want to optimize. you can choose the All Features option button or the Selected Features option from the Features Range area. All Features sorts all the features, Selected Features only sorts those features selected in the edit window.

The **Selected Features** option only becomes enabled if you select multiple features from the edit window *before* accessing the **Optimize Path** dialog box.

- 3. Choose a feature from the **Starting Feature** drop-down list. Path optimization will start from this selected feature.
- 4. Decide when to insert dimensions from your inspection plan into the part program by selecting the appropriate options from the **Dimensions** area. You can insert dimensions at the end of all the measured features by selecting **Insert at end** or as soon as possible after each measured feature by selecting **Insert as soon as possible**.
- 5. Determine whether or not you want to allow PC-DMIS to insert tip changes. If so, select the **Add Tip Changes** check box. The items in the **Tip Changes** area become enabled for selection and you should follow the bullet list here:
 - Select the **Only Defined Tips** check box if you want PC-DMIS to assign only defined tips to features. If an appropriate tip can not be found to measure a feature, then the feature will be assigned T?A?B?. This feature will be added to the list of **Features without tips** which is displayed to the user in the summary dialog at the completion of the Optimize Path process. If you clear this check box, PC-DMIS will also use undefined tips. Prior to execution, PC-DMIS will require that you calibrate any undefined tips.
 - Select the **Minimize Number of Tips** check box if you want PC-DMIS to use a minimal amount of tips to measure the features in your part program. PC-DMIS will only change the tip's angle when absolutely necessary. A progress bar at the bottom of the dialog box appears when you select this check box.
 - Select the **Ask if can't find Tip** check box if you want PC-DMIS to prompt you when it cannot determine the optimal tip for a given feature. This will allow you to manually specify the most appropriate tip.
 - Type an angle value into the **Conical Range of Tip Shank** box. This determines the conical tolerance for added tip changes. This allows PC-DMIS to utilize a tip that has a shank vector that is within the tolerance of the optimal vector angle for a given feature. For features such as points, lines, and planes there is a built in conical range of 90 degrees since a plane with a vector of 0, 0, 1 could be measured by t1a0b0 or t1a90b0. In the case of these features, PC-DMIS adds the user entered value to the built-in range. The proposed tip angle is also checked by running collision detection (silently) to determine if the tip will actually work.
 - Sort penalty in seconds for: MIP/MIH, PH9/PH10, PHS WRIST These values in seconds are an approximation of the time taken by a CMM to change tips for various categories of probes. The default penalties mean that all features measured with a given tip will be grouped together and sorted within that tip group. For example, If the penalty were set to zero, this would allow the Optimize Path process to sort features solely based on the distance travelled between features while completely ignoring tip changes.
- 6. Click **OK** to perform the path optimization; PC-DMIS does the following:

PC-DMIS Inspection Planner

- Takes the tip vector and the cone tolerance and determines the best tip angle for each feature. For example, the optimal tip angle for a cylinder will be based on the cylinder vector, which may or may not correspond to an exact tip angle.
- Sorts the features by the tips used to measure them.
- Determines the best path for the probe to take based on distances between features and the tip change.
- Adds dimensions either at the end of the program or after each feature.
- Adds constructed features as soon as possible.

See the "Dual Arm Path Optimization" topic for information on Dual Arm programs.

PC-DMIS will not sort across alignment or loadprobe commands. Additionally, PC-DMIS removes all MOVE/POINT commands, but preserves any motion commands or other parameters that may affect measurement, such as retract distance, prehit distance, etc.

Path Optimization ensures that features that have the <u>RMeas</u> option will not be measured prior to the features to which their measurement is relative.

Dual Arm Path Optimization

Path Optimization for dual arm programs are similar to single arm programs with a few exceptions. The **Dual Arms** area of the **Optimize Path** dialog box is enabled and the **Starting Feature** pull-down list is hidden. To complete Path Optimization for dual arms, follow the procedure described in "<u>Performing the Path Optimization</u>" and then complete the following steps:

- 1. Select the **Assign Arms** check box. The Optimize Path process will assign arms to each of the **Selected Features** (or **All Features**).
 - If all probe hits of a feature can be measured by Arm1, then it will be assigned to Arm1.
 - If Arm1 cannot measure a feature, but Arm2 can reach all of the probe hits that feature, then it is assigned to Arm2.
 - If neither arm can measure the feature, then Arm1 is assigned and the feature is added to the list of **Dual Arm Errors** / **Features that cannot be measured** which is displayed to the user in the summary dialog at the completion of the Optimize Path process.

- Dual Arms	
🔽 Assign Arms	
%Overlap to use:	25
OK	Cancel

Dual Arms are of the Optimize Path dialog box

2. Specify the Overlap percentage in the **%Overlap to use.** This controls how the machine volume is divided between the two arms. At 0%, each arm would only be allowed to measure features that are within the half of the machine volume that is accessible to that arm. At 100%, Arm1 would be assigned to all the features.
3. Click **OK** to begin the Path Optimization process. This displays the **Optimize Path Starting Features** dialog box. This allows you to specify the starting feature for each arm

1 Sta	rting Feature :	
	CIR1 = Auto Circle	-
12 Sta	rting Feature :	
	CIR2 = Auto Circle	-

Optimize Path Starting Features dialog box

Path Optimization Summary

Once the Path optimization has completed, the **Optimize Path Summary** dialog box shows the results of the path optimization.

mize Path Summary	
Path Length % Shorter after Optimization	
Probe Tip Errors Features without tips	
Uncalibrated tips	
ual Arm Errors	
Features that cannot be measured	

The dialog box reports the following information:

Path Length % Shorter after

Optimization – This value refers to the percent reduction of the optimized path length compared to the normal path length. For dual arm machines, it gives a percentage for both arms.

Probe Tip Errors – Features that were not assigned to a probe tip are listed in the **Features without tips** list. You may need to define new probe tips to ensure that each feature has a tip that can measure it. The **Uncalibrated tips** list shows the uncalibrated probe tips that you plan to use to measure features in your part program. You may need to calibrate these tips before executing the part program.

Dual Arm Errors – Features that the program was unable to measure by either arm will be included in this list.

Optimize Path Summary dialog box

Void Detection

Void Detection prevents hits from being taken in empty spaces (such as holes). This functionality has been added to these Auto Features:

- Auto Vector Point
- Auto Surface Point
- Auto Edge Point
- Auto Line
- Auto Plane
- Auto Circle
- Auto Round Slot
- Auto Cylinder

Without Void Detection, an auto feature may place hits in holes and other empty spaces in the CAD surface and the part.

PC-DMIS uses void detection if your hardware key (or portlock) has been programmed with the **IP measure** item. PC-DMIS automatically applies void detection to the generation of the probe hits when you create a supported auto feature by using the parameters from corresponding **Auto Feature** dialog box (such as **# hits**, **Start Angle** and **End Angle** for an auto circle). Any probe hits that would normally fall into a void are moved so that they reside on the surface of the selected feature, at least, a probe radius distance from any edge of that surface. Requested sample hits for Auto Circles or Auto Cylinders are also automatically generated with void detection.

The following examples show when Void Detection would be useful for accurately and safely measuring an Auto Feature. Hits denoted with an "X" are determined to be Voids and are corrected to the edge of the auto feature surface.



Void Detection for an Auto Plane Feature



Void Detection for an Auto Cylinder Feature

Automatically Inserting Move Commands

Once you import your part program and have finished Path Optimization, you should ensure that when the probe moves to measure your features, it will not collide with your part. Collision Avoidance is accomplished by inserting move commands. To do this, use PC-DMIS's **Auto Insert Move** menu option to automatically create clearance moves for a range of features:

Note: Move commands can be placed between the range of features specified, but not prior to the first feature. A clear path is assumed to the probe start position and the first feature.

1. Select the **Operation | Graphics Display Window | Auto Insert Moves** menu option. The **Automatically create clearance moves** dialog box appears.

Start	CON1	
End	CIR2	
Collision sa	lety [5
insert clear	ance moves	30
Delete exit	ting moves: F	7

Automatically create clearance moves

- 2. Select the first feature for the range of features from the Start list.
- 3. Select the last feature for the range of features from the **End** list.
- 4. Type a value in the **Collision safety** box. This value provides a buffer zone around the probe tip so that PC-DMIS considers close misses as collisions.
- 5. Type a value in the **Insert clearance moves** box. This value defines the distance that the probe moves away from the part when it detects a collision while trying to move the probe to the next feature. PC-DMIS attempts to go directly to the next feature, but compensates for collisions by inserting clearance move commands. It continues this process until it defines a collision free path to the next feature. More than one move command may be inserted between features.
- 6. Select the **Delete existing moves** check box if you want to delete any pre-existing move commands in the part program.

For Dual Arm programs, PC-DMIS will insert "Move Exclusive" commands as necessary to guard against the two arms colliding during execution.

Inspection Planner Parameters and Rules

The **Inspection Planner Default (IPD)** file is used to define the parameters for **Inspection Planner** within PC-DMIS. This file allows you to determine how to take hits from features within the **Inspection Plan**. Feature parameters are specified for Auto Features, Constructed Features, and Dimensions. You can also specify how you want to display comments and features.

The **Inspection Planner Rules (IPR)** script is used to specify rules for how automatic processes are performed on the **Inspection Plan**. Rules can be modified for certain criteria. For example, the number of hits taken on a circle based upon the diameter of the circle and so forth.

Creating and Modifying an Inspection Planner Default (IPD) file

To create a new **IPD** file or make changes to an existing IPD file, follow this procedure:

1. Select the **Edit | Preferences | Inspection Plan Defaults** menu option. The Modify Default Parameters dialog box appears.

The **Modify Default Parameters** dialog box is password protected if password protection has been enabled for other settings in PC-DMIS. See the "<u>Setup Options: General Tab</u>" topic in the core PC-DMIS reference manual for more information.

💑 Modify Default P	arameters		×
Default Parameters Fi	le Name		
C:\InspectionPlanner	/\default.ipd		•
Set As Default	Open	Create	

Modify Default Parameters – Inspection Planner Default File

 From the Default Parameters File Name drop-down select or browse to the file you want to modify or open. Click Browse... to open a select file dialog box if the IPD file is not already listed.

Default Parameters File Name	
C:\InspectionPlanner\default.ipd	¥
C:\InspectionPlanner\default.ipd	
Browse	

File Name list box - IPD

 Click the **Open** button to modify or open an existing IPD file. Or if you want to create a new IPD file, click **Create**. The **Default Parameters** dialog box opens for the selected or new IPD file.

ist of properties		
Auto Line		
Display Hits	YES	
Show Details	NO	
Coordinate Type	RECT	
Bound Type	UNBND	
Auto Move	NO	
Auto Move Distance	0.000000000	
Number of Hits	2	
Depth	0.000000000	
Thickness Type	THEO_THICKN	
Thickness	0.000000000	
Hit Type	BASIC	
Auto Plane		
Auto Circle		
Auto Cylinder		
Auto Edge		
Display Hits	NO	
Show Details	NO	
Coordinate Type	RECT	
Initial Hits	0	
Permanent Hits	0	
Measure Order	SURFACE	
Read Position On Error	NO	
Auto Move	NO	
Auto Move Distance	0.000000000 -	

Default Parameters for IP

- 4. To edit a parameter, from the right column, click on that parameter's value. A drop-down list becomes visible.
- 5. Select the drop down list, and finally choose a different value. These values may represent distance, amount, or some measured value. You can select values from option lists or toggle fields.
 - Option lists provide a list of choices relevant to the associated item.
 - Toggle fields provide only two choices, such as ON/OFF, YES/NO, or TRUE/FALSE.
- 6. Click the **Sort** check box if you want to sort the **List of properties** alphabetically.
- 7. Click the Collapse/Expand All button to collapse or expand the List of properties.
- 8. Click **OK** to open the **Save As** dialog box, or **Cancel** to abort any changes that have been made.
- 9. Click **Save** to save the IPD file.
- 10. Click **Set as Default** if you want to make the file listed in the **Default Parameters File Name** box the default file.
- 11. Click Exit when finished.

Inspection Planner Rules (IPR) script

IPR scripts are basic scripts that determine how features are measured within your part program. This script is applied as your Inspection Plan is imported into your part program.

The PC-DMIS Basic Script Editor can be used to create IPR scripts.



Basic Script Editor containing sample code for IP rules

The example in the above figure shows rules that will change the number of hits that are taken depending on the diameter of the circle.

To make changes to the Inspection Planner Rules (IPR) script, follow this procedure:

1. Select the Edit | Preferences | Inspection Plan Defaults menu option. The Modify Default Parameters dialog box appears.

The **Modify Default Parameters** dialog box is password protected if password protection has been enabled for other settings in PC-DMIS. See the "<u>Setup Options: General Tab</u>" topic in the core PC-DMIS reference manual for more information.

🔽 Use Rules Script	
Rules Script File Name	
C:\PCDMISW\Rules.ipr	
Set As Default Open	Create
	Exit

Modify Default Parameters – Rules Scripts Section

- 2. Select the **Use Rules Script** check box.
- 3. From the **Rules Script File Name** drop-down select or browse to the file you want to modify. Click **Browse...** to open a select file dialog box if the **IPR** file is not already listed.



File Name list box - IPR

- 4. Click **Open** to modify an existing **IPR** file or click **Create** to open the default **IPR** script. This will open the selected file in the **Basic Script Editor**. When using **Create** a new script will be populated with a default IPR script inside of the **Basic Script Editor**.
- 5. Edit your IPR script using the **Basic Script Editor**.
- 6. Click the **Save** Icon **I** to save your finished script.
- 7. Click **Close** to exit the **Basic Script Editor**.

Setting the Default IPR Script

- 1. Select the Edit | Preferences | Inspection Plan Defaults menu option. The Modify Default Parameters dialog box appears.
- 2. From the Rules Script File Name drop-down select or browse to the needed file.
- 3. Click **Set as Default** to make the file listed in the **Rules Script File Name** box the default file.
- 4. Click **Exit** when finished.

Appendix A: IP - Constructed Features

This section in the Inspection Planner documentation provides guidelines and information about the construction of features. For each CAD package, you have the ability to construct features based on existing Inspection Plan features.

The list below shows available construction operations. It discusses possible feature types under each operation section.

1. **Best Fit** - Constructs a Best Fit feature from the inputs. Using the **Best Fit** operation, you can create a *line, plane, circle, cylinder, cone, or sphere.* The following table lists how many inputs you will need to construct your feature.

Best Fit Feature To Construct	Number of Input Features Needed
Line	2
Plane	3
Circle	3
Cylinder	6
Cone	6
Sphere	5

2. **Best Fit with Recomp**- Constructs Best Fit with Recomp feature using inputs. At least one input must be a point Using the **Best Fit with Recomp** operation you can create a line, plane, circle, cylinder, cone, or sphere. The following table lists how many inputs you will need to construct your feature.

Best Fit Recomp Feature To Construct	Number of Input Features Needed
Line	2
Plane	3
Circle	3
Cylinder	6
Cone	6
Sphere	5

Best Fit and **Best Fit with Recomp** cylinders can be constructed from two circles. The input circles must be of type *Constructed Best Fit (BF)*, *Best Fit Recompensate (BFRE)*, or *Measured circles*. The total amount of hits in each circle must be at least three.

- 3. **Cast** Constructs the specified feature type at centroid of the input feature. Only one input feature of any type is needed. Using the Cast operation you can create a *point, line, plane, circle, cylinder, cone, or sphere.*
- Drop Constructs a point feature when first feature is dropped onto the second line feature. Two input features are needed. The 1st feature *can be any type*. The 2nd feature must be a *cone*, *cylinder*, *line*, or *slot*.

- 5. **Intersect** Constructs the specified feature intersection of the 2 input features. Using the **Intersect** operation, you can create a *point, line,* or *circle.*
 - Intersect Point Constructs a point at the intersection of the linear attributes of 2 features. The input types for either input feature should be a *circle, cone, cylinder, line* or *slot*.
 - Intersect Line Constructs a line at the intersection of two planes. The input features must be *planes*.
 - Intersect Circle Constructs a circle at the intersection of a circle, cone, cylinder, or sphere feature with a plane, cone or cylinder feature.
- 6. Mid Constructs a point, line, or plane midway between the two input features..
 - **Midpoint or Midplane** Constructs the point or plane feature midway between the centroids of *any input feature*.
 - **Midline** Constructs the line midway between *line*, *cone*, *cylinder*, *slot*, or *plane* input features.
- 7. **Offset** Constructs the specified feature based on the centroids of the input features and moved by the offset distance specified. The offset distance is given in terms of XYZ values. Using the **Offset** operation, you can create a point, line, or plane. The following table lists how many inputs you will need to construct your feature.

Offset Feature To Construct	Number of Input Features Needed
Point	1
Line	2
Plane	3

- 8. **Origin** Constructs a point, line, or plane at the alignment origin. No input features are needed.
- 9. **Parallel** Constructs a line or plane feature parallel to first input feature and passing through the second input feature.
- 10. **Perpendicular** Constructs a line or plane feature perpendicular to first input feature and passing through second input feature.
- 11. **Pierce** Constructs a point feature where the 1st input feature pierces the 2nd input feature. The order that the input features are selected is important. The 1st feature can be a *cone*, *cylinder*, *line*, *slot*, *circle* or *ellipse*. The 2nd feature can be a *cone*, *cylinder*, *plane*, *sphere*, *circle* or *ellipse*. If the 1st feature is a line, than the direction is important.
- 12. **Project** Constructs a point, line, plane, circle, cylinder, cone, or sphere onto the selected plane, or the current work plane, when no plane is specified.
- 13. **Reverse** Constructs a line, plane, circle, cylinder, cone or sphere with the same centroid and the same feature type as the input feature with the vector reversed.

Appendix B: Using the Generic Parser to Import ASCII Files

The Generic Parser (GP) is designed to parse the ASCII output from other CMM systems (like Metrolog). The ASCII output (file) may contain file header, comments, feature commands, file footer, etc. As long as the info is written line by line in the ASCII file, GP can parse it according to the user-defined rules provided through the Rule Set Wizard. After parsing it, GP will make calls to Inspection Planner to translate all the filtered-through info (like feature commands) and import into the active part program.

Note: Nine PC-DMIS feature types are supported by GP because they are also supported by Inspection Planner. The supported features are: POINT, EDGEPOINT, LINE, PLANE, CIRCLE, CYLINDER, SPHERE, SQSLOT (Square Slot) & RDSLOT (Round Slot). See "<u>Step 3: Feature Field Assignment and Mapping</u>" topic.

To begin importing an ASCII file as an Inspection Plan:

- 1. Select File | Import | ASCII File. An Open dialog box appears letting you select the needed ASCII file.
- 2. Browse to the directory containing your ASCII file.
- 3. Select the ASCII file, and click **Import**.

The **Importing** dialog box for your ASCII file opens. Create a rule set and complete process of parsing your ASCII file with the following steps:

- Importing an ASCII File
- Step 1: Excluding Data
- <u>Step 2: Defining Delimiters</u>
- Step 3: Feature Field Assignment and Mapping
- Previewing Your ASCII File

Importing an ASCII File

Rule set list	
SWRules[Default]	Create
Ruleset1 Ruleset2 Ruleset3	Edit
	Add
	Delete
	Set as default
Import to Part Program	Cancel

Importing dialog box for selected ASCII file

The **Importing** dialog box allows you to create, edit, add, or delete rule sets that can be used to evaluate your ASCII file. The selected rule set determines which information will be imported into your part program. Use the following options to select and apply rules for parsing your ASCII file.

Create - Opens Step 1 of the Rule Set Wizard. See "<u>Step 1: Creating a Rule Set</u>". Values of the selected Rule Set will be displayed, but if no Rule Set is selected, then no values will be displayed.

Edit - Allows you to edit the rule set selected from the Rule Set List.

Add - Browse via an **Open** dialog box and click **Open** to add a preexisting rule set. The rule set file will be copied into the designated rule file directory and a new entry will be displayed in the list box

Delete - Removes the selected rule set from the Rule Set List.

Set as default - Set the default rule set that will highlighted from the **Rule Set List**. This rule set will be used unless another rule set is selected. If no rule set is newly selected, the last used rule set is set as the default and is highlighted in the list box. The next time that you import an ASCII file the default rule set is highlighted.

Import to Part Program - The opened ASCII file is imported into the current part program:

• **Directly** - Imports the ASCII file using the selected rule set *without* using the Rule Set Wizard.

• **By wizard** - Opens Step 1 of the Rule Set Wizard. When you click finish on Step 3, the file will be imported using any newly specified rules.

Cancel - Aborts the ASCII Import process

All rule set files are stored in the same directory designated by the GP. The directory is named "AscImportRules", where the rule set files are named "*.ascimportrule".

Step 1: Excluding Data

The **Rules for parsing lines** provided in this step determines which lines of your ASCII file will included for importing into your part program. Use the following options to exclude data from import:

-1		
] 니		
-		
Containing SPHERE	After	Before
	Col.	SPHERE

Rule Set Wizard - Step 1

Skip file header - When this option is selected the specified **Number of lines** from the top of the ASCII file will be skipped. Therefore they will not be evaluated or imported into your part program.

Skip file footer - When this option is selected the specified **Number of lines** from the bottom of the ASCII file will be skipped. Therefore they will not be evaluated or imported into your part program.

For lines containing - Lines containing the text specified to the right will be evaluated on the following criteria:

Note: Qualifying search text is CASE specific

- Skip the entire line Entire line is excluded from being evaluated if qualifying text is present.
- **Truncate the strings after** Anything after the qualifying text will be excluded from being evaluated.
- **Truncate the strings before** Anything before the qualifying text will be excluded from being evaluated.
- **Truncate the strings until** Anything after the first qualifying text and prior to the text specified to the right of this option will be excluded from being evaluated.

Important: Use **Add** and **Remove** to update the criteria to the table on the right side of this dialog box. Multiple criteria can be used to evaluate your ASCII file.

Preview and Refresh - See the "Previewing the ASCII File" topic.

Next - Continue with <u>Step 2</u>.

Cancel - Returns to the Importing dialog box.

Step 2: Defining Delimiters

The **Delimiter** information provided in this step determines the columns for each of the parsed lines. Use the following options to parse your data and define units:

By column - Use this option for ASCII files that use fixed lengths for fields. This allows you to separate each field based on the length of the field. This may require a little trial and error to define the correct lengths for each field.

By column			
·	Col No.	Beginning	Ending
Beginning: 1	1	1	10
	2	11	17
Ending: 10	3	18	22
<u>`</u>	4	23	27
	5	28	32
Add >> << Remove Change >>			

Delimiters - By column

- Add Specify the **Beginning** and **Ending** characters of the field and click Add. The next column number will be assigned with a the **Beginning** and **Ending** values. Continue this process of adding columns until all the needed data is included in the appropriate columns.
- **Remove** Select the column you need to remove and click **Remove**. The column is removed from the list.
- **Change** Select the column you need to change, alter the **Beginning** and **Ending** values for the column and click **Change**. The column is updated with the new information.

By character - Use this option for ASCII files where fields are separated by tabs, spaces, commas or other characters. Select the separating character, tab or space.

By chara	cter	
Spe	cific character	Character List.
		,
🔿 Tab		
O Spa	ce(s)	
	Add >>	
	<< Remove	

Delimiters - By character

- Specific character Select this option and specify the one or more Specific characters that separate the fields in your ASCII file. Type the desired character and click Add to add it to the Character List. Select a character from the Character List and click Remove to remove a character.
- **Tab** Select this option and click **Add** if the fields of your ASCII file are separated by tabs. **Tab** is added to the character list.
- **Space(s)** Select this option and click **Add** if the fields of your ASCII file are separated by one or more spaces. **Space** is added to the character list.

Unit - This area is used to specify the units that are used for measured values:

- **MM** Millimeter
- CM Centimeter
- **DM** Decimeter
- Inch Inch

Preview and Refresh - See the "Previewing the ASCII File" topic.

Back - Returns to Step 1.

Next - Continue with <u>Step 3</u>.

Cancel - Returns to the Importing dialog box.

Step 3: Feature Type Mapping and Field Assignment

This step allows you map Feature Types to the features in your ASCII file. Additionally you can assign the field names to the delimited columns.

Feature Type		Feature Fields				
In PC-DMIS	In ASCII File	Field List		Field Name	Field Order	
POINT EDGEPOINT LINE PLANE CIRCLE CYLINDER SPHERE SQSLOT RDSLOT	FEAT/POINT FEAT/EDGEPOINT FEAT/LINE FEAT/PLANE FEAT/CIRCLE FEAT/CYLINDER FEAT/SPHERE FEAT/SQSLOT FEAT/RDSLOT	Feat Type Feat ID THEO_X THEO_Y THEO_Z THEO_I THEO_I THEO_J THEO_K *XTol *YTol *YTol *YTol *Tol ZTol Skip	Add >> << Remove	Feat Type Feat ID THEO_X THEO_Y THEO_Z THEO_I THEO_J THEO_J THEO_K	1 2 3 4 5 6 7 8	1

Rule Set Wizard - Step 3

Feature Type - Select the checkbox(es) of the feature type(s) that are to be imported. All of the available feature types are provided in the **Feature Type** list.

To map the feature type name:

- 1. Select the feature type to highlight the line.
- 2. Click in the list box under the heading "In ASCII file" on the same highlighted line.
- 3. Type the feature type name exactly as it appears in the ASCII file in the edit box. For example, the circle feature type name is "FEAT/CIRCLE" the example shown above.

Note: Without a feature type name defined in the ASCII file, there is NO way to differentiate which feature is point, circle, etc. if there are multiple feature types in the file. However, if there is only one feature type in the ASCII file, it is not necessary that the feature type name exists in the file, so the user does not have to specify it. The user just needs to check the check box to the left of the feature type and GP will apply that feature type to all of the lines in the ASCII file.

Feature Fields - The available fields for the selected **Feature Type** are displayed for assignment. Each field represents a valid PC-DMIS value for the selected feature type.

To assign a feature fields to the columns of the ASCII file:

- 1. Select a Feature Type.
- 2. Select the needed field name(s) from the **Field List**. To select consecutive fields, click the first item, press and hold down SHIFT, and then click the last item. To select nonconsecutive fields, press and hold down CTRL, and then click each item.
- 3. Click **Add** to add the field name to the list box on the right.

Note: You may also ADD or REMOVE fields by double-clicking the item in the **Field List** or the list box on the right.

PC-DMIS Inspection Planner

- 4. Use the **UP** and **DOWN** arrows to ensure that the field values appear in the order that the corresponding values appear in the ASCII file.
- 5. Select any unneeded field(s) from the list on the right and click **Remove** to remove that field name(s). To select consecutive fields, click the first item, press and hold down SHIFT, and then click the last item. To select nonconsecutive fields, press and hold down CTRL, and then click each item.

Note: PC-DMIS may not accept certain fields in the ASCII file that may be proprietary to a thirdparty CMM system provider's software. For such a field, the user can add the field called "Skip" to inform the GP to skip the column that contains this field.

Preview and Refresh - See the "Previewing the ASCII File" topic.

Back - Returns to Step 2.

Finish - This button will function according to how the Rule Set Wizard was started.

- **Create** The **Create new rule set** dialog box is opened. Provide the name of the new rule set in the **Rule Set Name** box.
- Edit The Rule Set Wizard is closed and any changes are applied to the rule set file.
- Import to Part Program (By wizard) The rule set is applied and the parsed ASCII file is imported into PC-DMIS as an Inspection Plan. If any changes have been made to the rule set, then you will also be prompted to save your changes.

Cancel - Returns to the <u>Importing</u> dialog box.

Previewing the ASCII File

As you make changes in each step of the Rule Set Wizard you can preview the affect that the rules will have on your ASCII file.

Preview - Selecting this checkbox will display the results of the evaluated file.

Refresh - Updates the view of your file based on the changes that you have made to the evaluation criteria.

No Rule Set Applied

Below is an example Preview of an ASCII Inspection Plan file where no rules have been applied. Any ASCII file that contains features can be used to import.

Note: The file used as an example is an Inspection Plan from SolidWorks with a .ip extension. The Generic Parser can work with any ASCII file with any extension.

No.	FeatType	Col1
1	Unknown	PCDIP/{Inspection Plan},1.0;
2	Unknown	UNITS/MM;
3	Unknown	FEAT/POINT,F1,14.75512,0.0,-27.61744,0.0,-1.0,0.0;
4	Unknown	FEAT/EDGEPOINT,F2,46.729183,0.0,0.0,0.0,0.0,1.0,0.0
5	Unknown	FEAT/LINE,F3,92.487095,0.0,-27.319991,114.180011,0
6	Unknown	FEAT/PLANE,F4,9.506888,11.536392,-21.0,0.0,0.0,1.0;
7	Unknown	FEAT/CIRCLE,F5,0.0,0.0,0.0,0.0,0.0,1.0,0.0,INNER;
8	Unknown	FEAT/CIRCLE,F6,0.0,0.0,0.0,0.0,0.0,1.0,0.0,INNER;
9	Unknown	FEAT/CIRCLE,F7,0.0,0.0,0.0,0.0,0.0,1.0,0.0,INNER;
10	Unknown	FEAT/CIRCLE,F8,0.0,0.0,0.0,0.0,0.0,1.0,0.0,INNER;
11	Unknown	FEAT/CYLINDER,F9,0.0,0.0,0.0,0.0,0.0,1.0,0.0,0.0,INN
12	Unknown	FEAT/RDSLOT,F12,188.135396,76.5,-2.060396,0.0,-1.0
13	Unknown	FEAT/SQSLOT,F13,63.529348,24.950494,-3.481529,0.7
14	Unknown	FEAT/SPHERE,F14,0.0,0.0,0.0,0.0,0.0,1.0,0.0,OUTER;
15	Unknown	ENDIP;

ASCII File with NO Rules applied

Application of Step 1 of Rule Set Wizard

Below is an example of the ASCII file after the values shown in <u>Step 1</u> were defined and **Refresh** was clicked. Lines 1, 2, 14 & 15 are excluded based on the defined criteria.

No.	FeatType	Col 1
1	Skip	
2	Skip	
3	Unknown	FEAT/POINT,F1,14.75512,0.0,-27.61744,0.0,-1.0,0.0;
4	Unknown	FEAT/EDGEPOINT,F2,46.729183,0.0,0.0,0.0,0.0,1.0,0.0
5	Unknown	FEAT/LINE,F3,92.487095,0.0,-27.319991,114.180011,0
6	Unknown	FEAT/PLANE,F4,9.506888,11.536392,-21.0,0.0,0.0,1.0;
7	Unknown	FEAT/CIRCLE,F5,0.0,0.0,0.0,0.0,0.0,1.0,0.0,INNER;
8	Unknown	FEAT/CIRCLE,F6,0.0,0.0,0.0,0.0,0.0,1.0,0.0,INNER;
9	Unknown	FEAT/CIRCLE,F7,0.0,0.0,0.0,0.0,0.0,1.0,0.0,INNER;
10	Unknown	FEAT/CIRCLE,F8,0.0,0.0,0.0,0.0,0.0,1.0,0.0,INNER;
11	Unknown	FEAT/CYLINDER,F9,0.0,0.0,0.0,0.0,0.0,1.0,0.0,0.0,INN
12	Unknown	FEAT/RDSLOT,F12,188.135396,76.5,-2.060396,0.0,-1.0
13	Unknown	FEAT/SQSLOT,F13,63.529348,24.950494,-3.481529,0.7
14	Skip	
15	Skip	

ASCII File with Step 1 Rules applied

Application of Step 2 of Rule Set Wizard

Below is an example of the ASCII file after the values shown in the **By character** area in <u>Step 2</u> were defined and **Refresh** was clicked. Columns have been added based on the comma separator (Col1-Col14).

N.,	FeatT	Col 1	Col 2	Col 3	Col 4	Col 5	Col 6
1	Skip						
2	Skip						
3	Unknown	FEAT/POINT	F1	14.75512	0.0	-27.61744	0.0
4	Unknown	FEAT/EDGEPOINT	F2	46.729183	0.0	0.0	0.0
5	Unknown	FEAT/LINE	F3	92.487095	0.0	-27.319991	114.180011
6	Unknown	FEAT/PLANE	F4	9.506888	11.536392	-21.0	0.0
7	Unknown	FEAT/CIRCLE	F5	0.0	0.0	0.0	0.0
8	Unknown	FEAT/CIRCLE	F6	0.0	0.0	0.0	0.0
9	Unknown	FEAT/CIRCLE	F7	0.0	0.0	0.0	0.0
10	Unknown	FEAT/CIRCLE	F8	0.0	0.0	0.0	0.0
11	Unknown	FEAT/CYLINDER	F9	0.0	0.0	0.0	0.0
12	Unknown	FEAT/RDSLOT	F12	188.135	76.5	-2.060396	0.0
13	Unknown	FEAT/SQSLOT	F13	63.529348	24.950494	-3.481529	0.707107
14	Skip						
15	Skip						



Application of Step 3 of Rule Set Wizard

Below is an example of the ASCII file after the features types and field names have been assigned in <u>Step 3</u> and **Refresh** was clicked. Feature types have been assigned based on the Feature Type field (Col1). Lines that have been successfully assigned to be imported as a feature type are displayed with blue text.

No.	Feature	Col 1	Col 2	Col 3	Col 4	Col 5	Col 6
1	Skip						
2	Skip						
3	POINT	FEAT/POINT	F1	14.75512	0.0	-27.61744	0.0
4	EDGEP	FEAT/EDGEPOINT	F2	46.7291	0.0	0.0	0.0
5	LINE	FEAT/LINE	F3	92.4870	0.0	-27.319	114.180
6	PLANE	FEAT/PLANE	F4	9.506888	11.5363	-21.0	0.0
7	CIRCLE	FEAT/CIRCLE	F5	0.0	0.0	0.0	0.0
8	CIRCLE	FEAT/CIRCLE	F6	0.0	0.0	0.0	0.0
9	CIRCLE	FEAT/CIRCLE	F7	0.0	0.0	0.0	0.0
10	CIRCLE	FEAT/CIRCLE	F8	0.0	0.0	0.0	0.0
11	CYLIND	FEAT/CYLINDER	F9	0.0	0.0	0.0	0.0
12	RDSLOT	FEAT/RDSLOT	F12	188.135	76.5	-2.060396	0.0
13	SQSLOT	FEAT/SQSLOT	F13	63.5293	24.9504	-3.481529	0.707107
14	Skip						
15	Skip						

ASCII File with Step 3 Rules applied

Glossary

IP: This is the acronym for PC-DMIS Inspection Planner.

- **IPD:** This is the acronym for Inspection Planner Defaults. Defaults are defined in a file that contains the parameters that are applied to the Inspection Plan.
- **IPR:** This is the acronym for Inspection Planner Rules. A rules script is created using Basic Script Editor within PC-DMIS. Rules are applied to the Inspection Plan.

Index

Α

Appendix
Constructed Features73
Generic Parser76
ASCII File
Importing77
Previewing82
ASCII File76
С
CATIA V5
Adding Feature to Plan20
Alignments
Rotating17
Translating16
Alignments15
Construction19
Editing your Inspection Plan21
Exporting4
Feature Creation
Circle13
Cylinder10
Edge Point9

Line	8
Plane1	0
Point	7
Round or Square Slot1	4
Sphere12	2
Inserting Comments1	9
Installing	2
IP_Commands Toolbar1	5
IP_Features Toolbar	6
IP_Tools Toolbar	3
Location Dimensions1	8
New Inspection Plan	3
Order Items in Plan	4
Plan Activation	6
Starting IP	2
Updating Features	5
CATIA V5	2
CATIA V5	2
Clearance Planes6	9
Collision Avoidance6	9
Constructed Features7	3

D	IF
Dual Arm Path Optimization66	IF
G	If
Generic Parser76	N
I	Ν
Importing ASCII Files76	C
Importing the Inspection Plan 62	C
Inspection Planner	C
CATIA V52	P
Default70	F
Default File62	F
Importing62	F
Menu Items23	R
Parameters70	F
Rules70, 72	
SolidWorks 22	
Unigraphics43	
Using within PC-DMIS62	
Inspection Planner1	
IP1	
IP Constructed Feature41	~
IP_Commands Toolbar15	S
IP_Features Toolbar6	S

P_Tools Toolbar3
PD70
PR72
Λ
Iodify Default Parameters72
)
Optimization67
Optimize Path64, 66
Path Optimization64, 66, 69
Path Optimization Summary67
Probe Tip Errors67
R
Rule Set Wizard
Step 1
Excluding Data78
Step 2
Defining Delimiters79
Step 3
Feature Type Mapping and Field Assignment81
6

SolidWorks

Alignments

Rotating37
Translating38
Alignments35
Constructing GD&T Features 39
Construction41
Creating Features26
Datum Features35
Deleting24
Exporting25
Feature Creation
Circle 32
Cylinder31
Edge Point 29
Line28
Plane 30
Point27
Round or Square Slot
Sphere 33
Inserting Comments 42
Installing 22
Location Dimensions
New Alignments
New Inspection Plan24

Starting IP22
SolidWorks22
U
Unigraphics
Alignments
Rotating56
Translating56
Alignments55
Construction59
Creating a New Plan44
Creating Features45
Datum Commands54
Displaying the Plan60
Exporting61
Feature Creation
Circle52
Cylinder50
Edge Point48
Line47
Plane49
Point46
Round Slot or Square Slot53

Showing the Plan.....24

Sphere	51
Inserting Comments	60
Installing	43
Location Dimensions	58
Starting IP	43

Tolerances57
Unigraphics43
Use Rules Script72
v
Void Detection68