




## PC-DMIS Operator Interface

Product presentation

2025-01-13 Customer Solutions Wetzlar

#### Introduction



- Powerful tool for convenient starting of PC-DMIS measurement routines
- Program start by mouse click or scanner (barcode, QR-code etc.)
- Execute measurement routines in single run, multiple run or pallet run
- Graphic user interface for intuitive operation
- measurement routines can be paused, aborted, or continued
- A progress bar shows the processing status



### **Single Run**

O PCE	OMIS-Oper	ator Interface 202	4.2 BETA							-	- ×	
File	List	Extras He	lp							Se	canner	
Singl	le run			Multiple run Pallet		Pallet r						
Filter (	(Measurei	ment routine)			Close measurement ro			utine after e	execution 🗹			
		Picture	Measurem				Directory					
1	0	007	Housir	g 737.PRG	C:\Factory\					00738		
2	Å		Pieuel-38468.PRG		C-VFactory/			038468				
D 3			Sphe	e30.PRG	C:\Factory\					00030		
4		O PCDMIS-Op	Elense erator Interface 2024	2 BETA	C15actorol							
		File List	Extras Help	)				00738				Scanne
÷		Single run		Mı	ıltiple run		Pallet run					
Č		Filter (Measu	rement routine)						Close	measurem	ent routine afte	er executio
	L			Measurement			Dire				Start code	
Wa	iting	1	607	Housing 7	37.PRG	C:\Factory\					00738	
		2	j	Pleuel-384	168.PRG	C:\Factory\					038468	
		р з		Sphere30.PRG		C:\Factory\					000030	
	4		Flansch 74		I7.PRG C:\Factory\							
•		•										
					tiele	_				_	_	
		waitin	g for mea	isuremen	. Job							

n 🗹

- Creation of measurement routine lists, which can be saved and called up again at a later point in time
- The lists can be changed / supplemented at any time
- Simple assignment and measurement routine selection using images
- Easy start of the measurement routine with a mouse click or scanner (barcode, QR-code etc.) → maximum security




#### **Multiple Run**

Single run	Multiple run	Pallet run	
View — List of measurement routines Overview			neasurement routine (variable CURR ement routine (variable CURCOMME
Measurement routine	e name	Measuring routine directory Co	mment
1 Housing 737.PF 2 Pleuel-38468.PP	RG C:\Factory\		
Sphere30.PRC	G C:\Factory\		
PCDMIS-Operator Interface 2024.2 I	BETA		- 0
File List Extras Help		00738	Scann
Single run	Multiple run	Pallet run	
List of measurement routines Overview		Send comment to the measur	neasurement routine (variable CURR ement routine (variable CURCOMME
Picture		Directory	Start code
D 1 0000	Multiplerun 1.QMA	C\\Users\Public\Documents\Hexagon\PCDMIS-Operator interface\Listen\	00738
2	Multiplerun 2.QMA	C-Wsers\Public\Documents\Hexagon\PCDMI5-Operator Interface\Listen\	038468
3	Multiplerun 3.QMA	C\Wsers\Public\Documents\Hexagon\PCDMIS-Operator Interface\Listen\	000030
4	Multiplerun 4.QMA	C\Users\Public\Documents\Hexagon\PCDMIS-Operator Interface\Listen\	

- Start several measurement routines with one mouse click
- Skipping measurement routines (lines) and colored display
- Creation of measurement routine2 lists that can be called up later
- Changing / supplementing this list is possible at any time
- Start the measurement routine list with a mouse click or scanner (barcode, QR-code etc.) → maximum security



#### **Pallet Run**



- Palettes can be easily defined
- Graphic representation of the palette
- Define and display unused instep spaces with a mouse click
- Creation of measurement routine lists for the pallet run, which can be called up at a later time
- Starting the measurement routine with a mouse click or scanner (barcode, QR-code etc.) → maximum security
- Graphic display of the measured instep spaces after the measurement



# Have we piqued your interest?

Simply download the software from our server and apply for a non-binding demo license.

https://downloads.ms.hexagonmi.com/PC-DMIS\_Solution\_Modules/PC-DMIS\_Operator\_Interface/

